## KING'S AUTO REPAIR & SERVICE PTE LTD

BLK 176, SIN MING DRIVE, #02-10, SINGAPORE 575721 TEL: 6457-8629 FAX: 6451-7651 UEN No 201923475D

DATE 17TH Mar 2021 OUR REF GBG 3191 B

FRIENDLY VEGETARIAN FOOD SUPPLIER

**BLK 421 ANG MO KIO AVENUE 10** 

TO #01-1165

**SINGAPORE 560421** 

**QUOTATION FOR VEHICLE GBG 3191 B - NISSAN URVAN** RE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## FOR NETT ITEMS

Quantity	Item	Unit Price (S\$)	Amount (S\$)
1	Front Panel / pp		1,221.50
1	Front Grille / DD		479.30
6pcs	Front Grille Clips / Nec	3.10	18.60 /
0,000		SUB-TOTAL	1,719.40
		LESS 10% DISCOUNT	171.94
		TOTAL	1,547.46

## FOR LABOUR CHARGES

ltem		Amount (S\$)
Panel Beating		600.00 <i>400</i>
Spray Painting		500.00250
Labour to remove and refit dashboard to facilitate		250.00 150
repair		
Labour to remove and refit aircon cooling coil, blower motor and to refill refridgerant		250.00 150
To replace advertisement sticker /Nec		400.00 150
To check wirings and lightings		50.00 7 C
Sealant for front panel		60.00 3 0
ocalant for none paris.	TOTAL	2,110.00

GRAND TOTAL FOR THIS QUOTATION 3,657.46

Repair day 3 days

P/P before paint photo.

Sun PINCLICK) 16/03/2021 To withou projul