

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD258H**AAD2103-064***Not Authorized**U/Snp & , T/loss ??*

Vehicle No.:

Chassis No.:

Vehicle Make:

12 MAR 2021

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD258H

VF1ABL15AUC282299

RENAULT

LATITUDE

04/03/2021

CHINA

20/11/2015

	PART		LIST	
1	BUMPER COVER REAR	\$	R ₁ 561.70	✓
1	BUMPER LOWER REAR	\$	mis 411.90	✓
1	BUMPER REFLECTOR LH	\$	B ₂ 16.60	✓
1	BUMPER BRACKET CTR REAR	\$	CM 98.10	✓
1	BUMPER BRACKET SIDE RH REAR	\$	mis 82.10	✓
1	BUMPER RETAINER RH REAR	\$	CM 59.80	✓
1	BUMPER BRACKET SIDE LH REAR	\$	CM 80.80	✓
1	BUMPER RETAINER LH REAR	\$	CM 54.20	✓
1	ABSORBER REAR	\$	NSP 217.30	X
1	BUMPER BEAM REAR	\$	R ₁ 547.80	✓
1	BUMPER BEAM BRACKET LH REAR	\$	R ₁ 114.50	✓
1	BUMPER BEAM BRACKET RH REAR	\$	R ₁ 114.50	✓
1	OUTER PANEL REAR (End Panel)	\$	R ₁ 745.80	✓
1	OUTER PANEL REAR (End Panel)TRIM	\$	DC 404.56	✓
1	SPARE WHEEL PANEL	\$	R ₁ 1,229.40	✓
1	SPARE WHEEL PANEL BRACKET LH	\$	R ₁ 70.60	✓
1	SPARE WHEEL PANEL BRACKET RH	\$	R ₁ 69.20	✓
1	FUEL FLAP	\$	PL 244.70	X
1	FENDER PANEL FRT RH	\$	N 437.10	X
1	FENDER PANEL FRT LH	\$	N 437.10	✓
1	FENDER PANEL INNER REAR LH	\$	R ₁ 1,241.60	✓
1	FENDER PANEL INNER REAR RH	\$	R ₁ 1,241.60	✓
1	SPARE TYRE BOARD	\$	680.90	?
1	FENDER INNER BOARD LH	\$	Return 561.40	✓
1	FENDER INNER BOARD RH	\$	✓ 561.40	✓
1	WHEEL HOUSE PRE ASSY LH (CENTER)	\$	1,241.60	?
1	WHEEL HOUSE PRE ASSY RH (CENTER)	\$	1,241.60	?
1	SILL PANEL OUTER LH	\$	N 1,902.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD258H**AAD2103-064**

1 SILL PANEL INNER LH	\$	N	483.20	X
1 SILL PANEL OUTER RH	\$	Bu	1,856.50	✓
1 SILL PANEL INNER RH	\$	N	371.10	X
1 TAILLAMP LH	\$	Br	401.40	✓
1 TAILLAMP RH	\$	Br	401.40	✓
1 EXHAUST REAR	\$	Bz	5,263.60	✓
1 EXHAUST BRACKET REAR	\$	Bz	24.80	✓
1 EXHAUST CAP REAR	\$	N	125.40	✓
1 BOOT REAR	\$	Bz	1,677.20	✓
1 BOOT BADGE 'RENAULT'	\$	N	82.40	✓
1 BOOT BADGE	\$	N	95.80	✓
1 BOOT REFLECTOR LAMP LH	\$	Br	277.70	✓
1 BOOT REFLECTOR LAMP RH	\$	Br	277.70	✓
1 BUMPER REFLECTOR LH	\$	Br	16.60	✓
1 BUMPER REFLECTOR RH	\$	Br	16.60	✓
1 WINDSCREEN REAR	\$	Shotford	1,010.80	✓
1 REAR PILLAR INNER TRIM- TOP	\$	D1	195.20	✓
1 REAR PILLAR INNER TRIM- LOWER	\$	D1	161.40	✓
1 BOOT HINGE LH	\$	Bz	254.20	✓
1 BOOT HINGE RH	\$	Bz	254.20	✓
1 BOOT STRUT LH	\$		145.10	?
1 BOOT STRUT RH	\$		145.10	?
1 BOOT LOCK LINKAGE	\$		20.60	?
1 BOOT LOCK LINKAGE HOLDER	\$		99.50	?
1 BOOT LOCK	\$	Tz	246.60	✓
1 BOOT LOCK CATCH	\$	Bz	41.70	✓
1 BOOT FINISHER	\$	Cm	344.70	✓
1 DOOR MOULDING REAR LH	\$	N	100.50	✓
1 DOOR MOULDING REAR RH	\$	N	100.50	✓
1 DOOR FINISHER REAR LH	\$		230.30	?
1 DOOR FINISHER REAR RH	\$		230.30	?
1 FENDER PANEL REAR LH	\$	Bu	1,933.20	✓
1 REAR RH FENDER PANEL	\$	Bz	1,933.20	✓
1 FENDER PANEL INNER TRIM REAR RH	\$	Rehm	671.45	✓
1 FENDER PANEL INNER TRIM REAR LH	\$	u	671.45	✓
1 BONNET	\$	N	1,312.70	X
1 BONNET LOCK	\$	D1	152.80	✓
1 BUMPER COVER FRT	\$	Bu	747.20	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD258H**AAD2103-064**

1 BUMPER ABSORBER FRT	\$	CM 394.68	✓
1 BUMPER BRACKET KIT FRT LH	\$	Sm 101.40	X
1 BUMPER RETAINER FRT LH	\$	Dir 101.40	✓
1 BUMPER BRACKET KIT FRT RH	\$	Sm 101.40	X
1 BUMPER RETAINER FRT RH	\$	Sm 101.40	X
1 BUMPER SUPPORT FRT	\$	Sm 10.70	X
1 BUMPER BRACKET FRT LH (Headlamp Lower)	\$	116.47	?
1 BUMPER BRACKET FRT RH (Headlamp Lower)	\$	116.47	?
1 BUMPER GRILLE LOWER FRT	\$	CM 147.00	✓
1 TOW COVER FRT	\$	Sm 60.90	X
1 WHEELARCH FRT RH	\$	Sm 191.40	X
1 RADIATOR GRILLE	\$	CM 969.90	✓
1 RADIATOR GRILLE BADGE 'RENAULT'	\$	Sm 225.36	✓
1 RADIATOR GRILLE FRAME	\$	CM 686.00	✓
1 FRAME FULL SUPPORT PANEL	\$	CM 592.70	✓
1 FRAME FULL SUPPORT BRACKET	\$	Sm 41.60	✓
1 A/C CONDENSER	\$	Pur 1,537.80	✓
1 FRONT BRACE PANEL	\$	Sm 177.22	✓
1 HEADLAMP LH	\$	mg CM 743.60	✓
1 HEADLAMP RH	\$	Sm 743.60	X
1 FENDER PANEL FRT LH	\$	N 437.10	X
1 FENDER BRACKET FRT LH	\$	N 106.40	X
1 FENDER PANEL FRT RH	\$	N 437.10	X
1 FENDER BRACKET FRT RH	\$	N 106.40	X
	\$	45,291.96	
	10% \$	4,529.20	
	\$	40,762.76	

Special Nett

1SET PARKING AID	\$	shar/na 700.00	✓
1SET REAR BUMPER CLIP	\$	na 66.00	✓
1SET BUMPER BRACKET CTR CLIP	\$	na 33.00	X
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	na 20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na 10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	na 20.00	X
1SET BONNET LOCK NUT	\$	na 60.00	X
1SET BUMPER LOWER REAR CLIP	\$	na 66.00	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2103-064**SHD258H**

1 EXHAUST MOUNTING REAR	\$	Tr	17.82	✓
1 REAR BOOT STICKER 'Trans-cab'	\$	na	80.00	30sn
1 REAR BOOT STICKER '6555-3333'	\$	na	80.00	30sn
1 BUMPER CLIP FRT	\$	na	85.00	66
1 BUMPER RETAINER CLIP FRT	\$	na	70.00	X
1 BUMPER GRILLE LOWER CLIP	\$	na	70.00	X
1 BUMPER FOG LAMP GRILLE CLIP	\$	na	65.00	X
1 LICENSE PLATE WITH HOLDER FRT	\$	na	120.00	45sn
2 WINDSCREEN SEALANT	\$	na	150.00	✓ 40sn
1 WINDSCREEN MOULDING	\$	na	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	NR	130.00	30sn
TOTAL	\$		1,572.82	
TOTAL PARTS	\$		42,335.58	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	2520	3,000.00	2520
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2800	3,000.00	2800
To Rust-Proofing Of The Affected Areas.	\$	✓	170.00	
To reinstall rear bumper parking sensor.	\$	600	170.00	
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	600	170.00	
To repair and realign rear exhaust pipe.	\$	} 800	170.00	
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$		170.00	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	170.00	1200

AAD2103-064

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD258H

To transfer of rear windscreen fittings and conduct
water seepage test. \$ 170.00 1201

To check steering geometry and computer wheel
alignment \$ 220.00 601

To Check Electrical Lighting Concerned. \$ 170.00 401

TOTAL \$ 7,580.00

Over All Total \$ 90,678.34

(LUMP SUM)

Repair Days

20 DAYS ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: