



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2105764

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 17/08/2021
Reference CC6/CTI21003335/Uea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMU 9392U
Insured Veh. SJN 9023H
Claim No. SNM21D201495/C02
Policy No. DMPCSNW00043472101
Accident Date 11/03/2021
Inspection Date 15/03/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21003335/Uea3q2 Date: 17/08/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 9023H	Veh. Inspected	SMU 9392U	
Policy No.	DMPCSNW00043472101	Coverage (\$)	0.00	
Claim No.	SNM21D201495/C02	Excess (\$)	0.00	
Assign From		Assign Date	15/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A4 (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WAUZZZ8K7BA009179	Colour	GREY	
Odometer	104470 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	PIRELLI	7 mm	
L/H Front Tyre	245/40 R18	PIRELLI	7 mm	
R/H Rear Tyre	245/40 R18	PIRELLI	7 mm	
L/H Rear Tyre	245/40 R18	PIRELLI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/03/2021	Inspection Date	15/03/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 9392U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED / CUT	2,219.00	2,200.00
1	FRONT BUMPER SIDE RETAINER O/S	CRACKED	105.00	66.00
1	SET FRONT BUMPER CLIPS	NECESSARY	60.00	50.00
1	FRONT BUMPER FOG LAMP O/S	CRACKED	620.00	172.00
1	FRONT BUMPER FOG LAMP GARNISH O/S	TWISTED	205.00	145.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	713.00	-
1	HEADLAMP O/S	CRACKED	4,850.00	1,308.00
1	HEADLAMP LOWER BRACKET O/S	CRACKED	395.00	118.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	1,250.00	-
1	FRONT GRILLE	CRACKED	1,480.00	706.00
1	FRONT GRILLE LOGO	NOT NECESSARY	115.00	-
1	FRONT FENDER O/S	BENT / BUCKLED	1,280.00	990.00
1	FRONT FENDER INNER SHIELD O/S	DEFORMED / TORN	292.00	240.00
1	SET FRONT FENDER INNER SHIELD CLIPS O/S	NECESSARY	60.00	60.00
1	FRONT SPORT RIM O/S	NOT NECESSARY	1,200.00	-
	LESS 5% DISCOUNT		-	-302.75
			14,844.00	5,752.25
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	30.00
	TO CONDUCT WHEEL ALIGNMENT .	NOT NECESSARY	120.00	-
	TO REFILL AIR CON GAS .	NOT NECESSARY	120.00	-
	TO RESET & REPROGRAMME SYSTEM.	NOT NECESSARY	180.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL .		1,080.00	500.00
	TO PUTTY & SPRAY PAINTING .		1,000.00	600.00
			2,550.00	1,130.00
	GRAND TOTAL		17,394.00	6,882.25



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,500.00
---	--	--	----------

Report Ref No. CC6/CTI21003335/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMU 9392U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMU 9392U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMU 9392U

RE-INSPECTION

