



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

LKK

Date : 12/03/2021

Attn: The Motor Claims Department

Your Insured veh no :S350P

ERGO Insurance Pte Ltd

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

WITHOUT PREJUDICE

(By Email Only)

Veron 100Y23180743

Dear Sir / Madam

Estimate Cost of Repair Toyota Dyna No GBE 1668 S & YM9578 B ON 09/03/2021 @092000

To Supply:-

1pc	Front body panel <i>Dented</i>		\$ 1,105.10	✓
1pc	Front grille <i>None</i>	1783.20	\$ 81.10	✗
1pc	Front panel garnish centre <i>None</i>		\$ 299.10	✗
1pc	Front side mirror assy LH <i>cut</i>	1337.40	<u>\$ 1,139.20</u>	295
1pc	Front logo <i>None</i>		\$ 98.10	✓
1pc	Front windscreen glass rubber <i>None</i>		\$ 285.00	✓
			\$ 3,007.60	
		less	25% \$ 751.90	
			\$ 2,255.70	

To dismantl & replace damage parts, panel beat where necessary

\$ 780.00 500

To putty, apply primer & spray paint on the affected portion.

\$ 680.00 250

labour charge to remove & refix windscreen

900

\$ 120.00 ✓

To check wiring functions.

\$ 80.00 30

\$ 3,915.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adnan
h/s 05/04/21
04 Days
Total: 2237.40
h/s: 1.81c.