

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5719S**AAD2103-58***Not Notified
L/Sing \$1200/-*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

12 MAR 2021**SHC5719S**

VF1ABL15AUC281617

RENAULT

LATITUDE

10/03/2021

AIG

12/06/2015

PART

- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER BRACKET SIDE LH REAR
- 1 BUMPER RETAINER LH REAR
- 1 BUMPER BEAM REAR
- 1 BUMPER BEAM BRACKET LH REAR
- 1 BUMPER BEAM BRACKET RH REAR

LIST

\$	Bu	561.70	✓
\$	nd/lw	411.90	✓
\$	sl	98.10	}
\$	sl	82.10	
\$	sl	59.80	
\$	sl	80.80	
\$	sl	54.20	
\$	n	547.80	
\$	n	114.50	
\$	n	114.50	
\$		2,125.40	
10% \$		212.54	
\$		1,912.86	

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1SET BUMPER BRACKET CTR CLIP
- 1SET BUMPER BRACKET SIDE CLIP RH RR
- 1SET BUMPER RETAINER RH CLIP RR
- 1SET BUMPER BRACKET SIDE CLIP LH RR
- 1SET BUMPER RETAINER CLIP LH RR
- 1SET BUMPER LOWER REAR CLIP

\$	sl	700.00	x
\$	nn	66.00	✓
\$	nn	33.00	x
\$	nn	10.00	x
\$	nn	20.00	x
\$	nn	10.00	x
\$	nn	20.00	x
\$	nn	66.00	✓
TOTAL \$		925.00	
TOTAL PARTS \$		2,837.86	

LABOUR

Trans-cab Auto Services Pte Ltd**AAD2103-58**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5719S

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>2200</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>2000</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>600</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>5</i> 170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>5</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>5</i> 170.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>5</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>5</i> 220.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>5</i> 170.00	<i>X</i>

TOTAL \$ 7,580.00**Over All Total \$ 12,330.72****(LUMP SUM)****Repair Days***2 days*
20 DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: