

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD69L**AAD2103-059***Not Noted*
*11 Sep 2006*Vehicle No.: *12 MAR 2021*

Chassis No.:

Vehicle Make: *Knocking And Straight*Vehicle Model: *Can Remove And Renewal Ch Parts*Date of Accident: *The Same*

Third Party Insurer :

Date of Registration : *The Adopted Area***SHD69L**

VF1ABL15AUC282224

RENAULT

LATITUDE

10/03/2021

AIG

03/08/2015

PART

- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER BRACKET SIDE LH REAR
- 1 BUMPER RETAINER LH REAR
- 1 BUMPER BEAM REAR
- 1 BUMPER BEAM BRACKET LH REAR
- 1 BUMPER BEAM BRACKET RH REAR
- 1 BUMPER REFLECTOR LH

LIST		
<i>Bn</i>	561.70	✓
<i>Ndlm</i>	411.90	✓
<i>SL</i>	98.10	X
<i>SL</i>	82.10	X
<i>SL</i>	59.80	X
<i>DIT</i>	80.80	✓
<i>SL</i>	54.20	X
<i>B</i>	547.80	✓
<i>H</i>	114.50	X
<i>H</i>	114.50	X
<i>CM</i>	16.60	✓
	2,142.00	
10%	214.20	
	1,927.80	

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1SET BUMPER BRACKET CTR CLIP
- 1SET BUMPER BRACKET SIDE CLIP RH RR
- 1SET BUMPER RETAINER RH CLIP RR
- 1SET BUMPER BRACKET SIDE CLIP LH RR
- 1SET BUMPER RETAINER CLIP LH RR
- 1SET BUMPER LOWER REAR CLIP

	<i>mit / Shan</i>	700.00	<i>400.00</i>
	<i>me</i>	66.00	✓
	<i>nn</i>	33.00	X
	<i>nn</i>	10.00	X
	<i>nn</i>	20.00	X
	<i>nn</i>	10.00	X
	<i>nn</i>	20.00	X
	<i>nn</i>	66.00	✓
TOTAL		925.00	
TOTAL PARTS		2,852.80	

LABOUR

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD69L

AAD2103-059

	Repair Days	20 DAYS
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 22d
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00 20d
To Rust-Proofing Of The Affected Areas.	\$	170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 6d
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 X
To repair and realign rear exhaust pipe.	\$	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 X
To check steering geometry and computer wheel alignment	\$	220.00 X
To Check Electrical Lighting Concerned.	\$	170.00 10d

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL \$ 7,580.00**Over All Total \$ 12,360.60****(LUMP SUM)**