

TRANS EUROKARS PTE LTD

ESTIMATE COST OF REPAIRS

CHINA TAIPING (SINGAPORE) PTE LTD		NAME : Mr Zhao Bingfeng		WIP : 30483				
3 ANSON ROAD		ADDRESS : Blk 79 Poh Huat Road		EXCESS :				
#16-00 SPRINGLEAF TOWER		#03-24		DATE: 4-Dec-20				
SINGAPORE 079909		Singapore 546787						
ATTN. :		TEL : 93833521 / bill.zhao@kenyon.com.sg						
FAX :								
VEH NO :	SMS7429Y	DATE IN :		CONTACT PERSON :	Jess 8128 9802			
CHASSIS NO :	JM6GL1072K0315396	MILEAGE :		TYPE OF CLAIM :	3RD PARTY CLAIM			
MODEL :	MAZDA 6	DATE REG:	12-Mar-20	POLICY NO. :				
NATURE OF WORKS								
Parts Description								
NO	PART NO.		QTY	1st	2nd	REVISED	PRICES	
1	BUMPER,FRONT		MGSJ8-50-031 BB	1			-	1,211.90
2	PLATE RH,SEAL-F.BUMPER		MGSH7-50-1U0	1			-	78.90
3	COVER RH,BUMPER		MGSH7-50-103	1			-	30.20
4	RETAINER RH,BUMPER		MGHP9-50-0T1B	1			-	17.10
5	GROMMET @ 2.90		MGHP9-50-0Z5	2			-	5.80
6	RIVET @ 4.00		MS51S-51-833	8			-	32.00
7	MESH,GRILLE		MGSH7-50-719	1			-	180.40
8	BRACKET RH,BUMPER		MGSH7-50-151	1			-	37.10
9	MOULD RH,FRONT		MGSH7-50-7J0D	1			-	251.40
10	MOULD LH,FRONT		MGSH7-50-7K0D	1			-	251.40
11	BRACKET,GRILLE-RADIATOR		MGSH7-50-717A	1			-	95.00
12	RIVET @ 9.20		MTK21-50-355	6			-	55.20
13	BRACKET RH,FRT.BUMPER		MGSH7-50-153	1			-	14.50
14	RIVET @ 4.00		MS51S-51-833	8			-	32.00
15	PANEL RH,FENDER-FRT		MGHP9-52-111A	1			-	383.70
16	GUARD RH,MUD		MGRF2-56-130	1			-	114.30
17	STAY RH,FENDER		MGHZ9-52-1R0A	1			-	48.30
18	BODY RH,FRONT DOOR		MGHY0-58-02XJ	1			-	975.20
19	HINGE RH,DOOR-UPPER		MKD53-58-210A	1			-	37.40
20	HINGE RH,DOOR-LOWER		MD461-59-210B	1			-	37.80
21	FASTENER RH-NECESSARY		MTK48-58-762	1			-	9.20
22	FASTENER @ 3.70 - WEATHERSTRIP		MBC1D-58-762	54			-	183.60
23	STRIPE NO.1 RH,BODY SIDE		MGRTE6-50-8V1A00	1			-	11.00
24	STRIPE NO.3 RH,BODY SIDE		MGRTE6-50-8V3A00	1			-	12.90
25	MOULD RH,FRT.BELT		MGHP9-50-640F	1			-	96.00
26	SEAT RH,HANDLE-OUT		MKD53-58-414	1			-	5.70
27	GROMMET @ 2.40		MBF67-51-261	2			-	4.80
28	CHECKER,DOOR		MGBFN-58-270	1			-	47.20
29	GROMMET @ 3.80		M9991-00-503	1			-	3.80
30	TAPE SEAL @ 2.40		MKB7W-58-883	2			-	4.80

31	FASTENER @ 3.20	MGD7A-50-EA1	2			-	6.40
32	GROMMET @ 3.00	MGJ6A-58-975	9			-	27.00
33	CLIP @ 2.40	MGS1D-58-315A	2			-	4.80
34	COVER,HOLE DOOR @ 5.20	MGHP9-58-972	2			-	10.40
35	FASTENER @ 7.20	MGJ6A-68-AB1	18			-	129.60
36	FASTENER @ 2.40	MGE4T-68-865A	2			-	4.80
37	BODY RH,DOOR MIRROR	MGSB9-69-121A	1			-	475.90
38	HOUSING RH,DR MIRROR	MB63B-69-1N1 64	1			-	128.40
39	GLASS & HOLDER RH,MIRROR	MB63C-69-1G1	1			-	282.50
40	COVER(R),HOLE DR MIRROR	MGHP9-69-115	1			-	13.30
41	GARNISH RH,SAIL-OUT	MGJR9-69-15YB	1			-	116.30
42	WHEEL,DISC	M9965-16-7570	1			-	1,196.80
43	CAP,CENTER RIM	MKD51-37-190	1			-	21.60
44	VALVE,AIR	M9963-60-4140	1			-	6.70
45	HUB,WHEEL FRT	MKD35-33-04XF	1			-	566.70
46	COVER RH,DUST-BRAKE	MKD45-33-261B	1			-	31.90
47	KNUCKLE RH,STEERING	MGBFN-33-021	1			-	378.10
48	ARM RH,LOWER	MG46C-34-300J	1			-	503.90
49	DAMPER RH,FRONT	MGBJD-34-700A	1			-	392.40
50	BEARING,FRONT STRUT-DAMPER	MB45A-34-38XA	1			-	55.80
51	DUST COVER-DAMPER	MB45A-34-015C	1			-	36.30
52	STOPPER-DAMPER	MGBFN-34-111	2			-	58.20
53	RUBBER,SPRING	MKA0G-34-0A3	1			-	23.40
54	UNIT RH,HEADLAMP	MGSK4-51-031A	1			-	4,759.30
55	PROTECTOR RH,HEAD,LAMP	MGRF5-51-065A	1			-	102.00
56	TANK,WASHER	MGHR1-67-481	1			-	109.80
	TOTAL PARTS					-	13,710.90
	TOTAL PARTS COST					-	13,710.90
SUPPLEMENTARY							
NO	PARTS NO		QTY	1st	Supp	REVISED	PRICES
1							
2							
	TOTAL PARTS						-
							-
	TOTAL PARTS COST						-
Labour Description							
1	SUB	REPLACE FRT BUMPER (1), RHF FENDER (0.5), RHF DOOR (1). REPAIR RHR DOOR (0.5), RHR FENDER (0.5) AND AREAS AFFECTED BY THE ACCIDENT.				-	2,640.00
2	SUB	SPRAY FRT BUMPER (1), BONNET (1), RHF FENDER (1), RHF DOOR (1), RHF DOOR (1), RHR FENDER (1), RH SIDE MIRROR COVER (0.25)				-	4,095.00

3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU)	-	200.00
4	MZ-BR-DOORME	TRANSFER DOOR MECHANISM (0.5).	-	630.00
5	MZ-BR-AXNSUP	REPLACE THE DAMAGE SUSPENSION ITEMS ON THE RHF SECTION (1).	-	945.00
6	SUB	SUPPLY 1 PC TIRE (NETT).	-	450.00
7	MZ-BR-WHEBAL	REPLACE THE RHF SPORT RIM & TIRE. PERFORM WHEEL BALANCING (MIN 80.00).	-	120.00
8	MZ-BR-WHEALI	CONDUCT 4 WHEEL ALIGNMENT (1).	NETT	560.00
9	MZ-BR-ELECTR	ELECTRICAL CHECK FOR PROPER FUNCTION.	-	250.00
10	MZ-BR-REPROG	REPROGRAM AFTER THE REPAIR WORKS.	-	350.00
11	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	NETT	100.00
12	MZ-BR-SUNDRI	SUNDRIES.	-	100.00

TOTAL LABOUR		10,440.00
TOTAL PARTS		13,710.90
TOTAL		24,150.90
LESS EXCESS		-
TOTAL AFTER EXCESS		24,150.90
GST 7%		1,690.56
GRAND TOTAL		25,841.46

SUPPLEMENTARY LABOUR DESCRIPTION

1		#N/A	-
2		#N/A	-

SUPPLEMENT LABOUR	-	-
SUPPLEMENT PARTS	-	-
TOTAL SUPPLEMENT	-	-
	-	-
	-	-
GST 7%	-	-
GRAND TOTAL	-	-

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED

TRANS EUROKARS PTE LTD

.....
ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS
LABOUR CHARGES.

Authorised Signature