. 5	ASSIGNMENT
3	Van No. STD 6-8860 / YEROOD 2/1/14
From: Date:	Veri IVO.
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD /TP/ WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: 50 (1 \$ \$ 60)	Make: Trysta. Comry c.c 2494
at Workshop m/s Yew hee	Colour A.G: Insured / Std / NI / NA
of	Sp.Reading 133227 T/Radio: Insured / Std / NI / NA
Insured: SL1832FR	Eng/No:
Policy No.	C/NO: MRUS3AK500400729
Claims No. C1000 9372 KY	Gen. Cond. Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil (S/Rim / STD A/Rim or
+	Tyre Size: F: 215-/5-(-1)
(Policy Condition)	R:
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC) OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value:	Front / Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 0 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 9/3/2/ D.O.I. 22/3/2/
Lum Sum: % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS 27 A 4	Des. of Damages : Frt. / Rear / O/S / N/S / U/C / Rooftop or
Vehicle:	
Date: Person Contacted: 27 11k-	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction Be Action / Instruction	h
1-11 1/2 -2110	0 / 0 1 - 10 / 100
1/3/4 4/5 \$ 3450 Cont	(Red 6833.55, 66%)
	(Red 6833.55, 66%)
	_
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 4
1) : Final Report	Resurvey No. of Trip: 1 Survey Fee:
Date/Time, File Return to?	Transportation:
2) 29/3 - typist Ac	dd Fee: : Site Insp (\$)s+Rs,si
	: Interview (\$) Photos
Report Format : TP	: Tech. Invs (\$) Others
The same a serial field. The design of the serial series are	,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

The information contained herein is correct as at 09 Mar 2021

Singapore NRIC

235H

SDG8860Y

No

09 Mar 2021

TOYOTA

CAMRY 2.5 AT

Silver

2013

2ARU074438

MR053AK5004007297

133.0 kW (178 bhp)

\$28,050.00

02 Jan 2014

02 Jan 2014

\$31,270.00

Yes

01 Jan 2024

\$18,762.00

01 Jan 2024

B - Car (1601cc & above)

10

\$79,300.00

\$22,297.00

\$41,059.00

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources







Post an Advertisement Sell it yourself! Advertise it at just \$68 until it's SOLD! Nov 2007 White Porsche GT3.1 2nd Owner At \$460k.

Very Low Mileage, 2nd Owner, Stuttgart Maintained, Immaculate New COE Till 2027 Direct Owner StarAd



Browse by Category ~ 3 vehicles

Post an Ad

Toyota Camry

Ways of Selling

Sort by Date Posted

✓ 20 results/page ✓

Advertiser Login

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage Veh Type

Submit (

Search Selection

Toyota Camry

2014

Any

Available

Toyota Camry 2.5A

\$53,000

\$10,940 /yr

25-Aug-2014

2,494 cc

149,000 km

Luxurv

Available DIRECT OWNER

Only SMS And WhatsApp Message! Powerful And Comfortable Spacious Sedan With Lots Of Space For Whole Families. Well Maintained I... Posted: 21-Mar-2021 Tags: 2014 Toyota Camry, Toyota Camry, Toyota, Camry



Toyota Camry 2.0A

\$56,800

\$11,720 /yr

28-Nov-2014

1,998 cc

113,638 km

Luxury Available

1 Owner Unit. One Of The Most Sought-After Luxury Sedan Model. Well Known For It's Reliability, Smooth Transmission, Excellent Lengt.

Posted: 18-Mar-2021 Tags: 2014 Toyota Camry, Toyota Camry, Toyota, Camry



Tovota Camry 2.5A

\$53,800

\$11,710 /yr

25-1un-2014

92.571 km

Luxury

Available

Low Bank Interest Rate 1.88% And Very Easy In House Loan Available! High Trade In, Low Mileage 13,800KM Yearly, Well Taken Care.

Posted: 17-Mar-2021 Tags: 2014 Toyota Camry, Toyota Camry, Toyota, Camry

Save this search criteria, to get email alerts whenever a match is found

Model

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

For old advertisements, view Expired ads

✓ results/page

Home New Cars Used Cars Rental Cars Sell My Car Directory Products Insurance Article Forum Resources

sqCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota Camry, Toyota Camry Singapore, used Toyota Camry Singapore, used Toyota Camry, used Vehicles Singapore or even buy used Toyota Camry Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61 Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER: BUDGET DIRECT INSURANCE SINGAPORE

PARTICULARS OF CLAIM

Claim Type:

5103713396-02

LAI LAIZHENG

Date of Loss:

YTKB/TP/2103/003

Policy No:

SDG8860Y

Driveable?

Ref. No:

9/3/2021 no

Vehicle Reg. No.:

19/9/1981

Third Party Vehicle No.:

SLJ8325R

Driver Age: Any Injuries?

TP

Contact No:

98737321

Insured/Claimant:

Driver:

LAI LAIZHENG

Make/Model:

Toyota, Camry

Vehicle Reg. Date:

02 Jan 2014

Vehicle Colour:

RED

Engine Number:

2ARU074438

Chassis No:

MR053AK5004007297

Odometer:

Total Loss?

Est. Duration of Repair(Day) 10

Description of Accident/loss

CHAIN COLLISION

Remarks:

Present Location:

Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS	Amount
Parts	6,373.18
Miscellaneous Items	0.00
Labour	1,540.00
Paintwork Labour	975.00
Towing	0.00

Gross Total(S\$): GST 7.00%(S\$): 10,283.55 8,888.18 622.17

Nett Amount(S\$):

9,510.35

This claim is handled by: may chai

Not Arthurul Llel Ws # 3450 | Atheren

REPAIR DETAILS

Estima	ates On Pa	rts			
No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	TAILGATE R	1,031.00	-25.00	773.25 X
2	1	TAILGATE EMBLEM 12C	59.00	-25.00	44.25
3	1	TAILGATE GARNISH U 7	310.00	-25.00	232.50 X
4	1	TAILGATE HINGE RH A 7	129.00	-25.00	96.75 🗶
5	1	TAILGATE HINGE LH 1	129.00	-25.00	96.75 X
6	1	TAILGATE TOP SPOILER SUC	0.00	-25.00	0.00 🗙
7	2	REAR NUMBER PLATE LAMP 1	124.00	-25.00	93.00 🗡
8	1	TAILGATE LOCK 17	382.00	-25.00	286.50 X
9	1	TAILGATE INNER BOARD 1	440.00	-25.00	330.00
10	1	TAILGATE INNER RUBBER 1012	187.00	-25.00	140.25
11	1	REAR BUMPER	573.00	-25.00	429.75
12	1	REAR BUMPER SIDE RETAINER RH 41	105.00	-25.00	78.75 ×
13	1	REAR BUMPER SIDE RETAINER LH 304	105.00	-25.00	78.75
14	1	REAR BUMPER REFLECTOR RH 19	57.00	-25.00	42.75 X
15	1	REAR BUMPER REFLECTOR LH 11	57.00	-25.00	42.75
16	1	REAR BUMPER REINFORCEMENT	382.00	-25.00	286.50
17	1	BOOTLAMP RH 17	311.20	-25.00	233.40
18	1	BOOTLAMP LH 17	311.20	-25.00	233.40
19	1	TAILLAMP RH 17	377.00	-25.00	282.75
20	1	TAILLAMP LH CAL	377.00	-25.00	282.75
21	1	END PANEL 😥	619.00	-25.00	464.25
22	1	END PANEL TOP GARNISH CM 265.13	310.00	-25.00	232.50
23	1	REAR LH FENDER 1	999.00	-25.00	749.25 🗶
24	1	REAR EXHAUST PIPE 1	937.00	-25.00	702.75

Total Parts	(S\$)	6,233.55

No.	Qty	Particulars	Amount	%Disc	After
					Disc
1	1	REAR NUMBER PLATE	35.00	0.00	35.00
2	1	REAR CAMERA	300.00	0.00	300.00
3	1 Sef	REAR BUMPER SENSOR	300.00	0.00	300.00 200
1	10	END PANEL TOP GARNISH CLIP 17	50.00	0.00	50.00 🗶
5	10	REAR BUMPER CLIP MAN	50.00	0.00	50.00
	IPC	lear bumper lower spoiler	Cre 800.00		800-00 600
	110	120	Sub Total (S\$)		735.00

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	0.00	180.00
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00
3	1	To Transfer Rear Tailgate.	80.00	0.00	1 7 80.00
4	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	100.00	0.00	100.00
5	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To	1,100.00	0.00	1,100.00

No.	Qty	Particulars An	nount	%Disc	After Disc
		Re-adjust to the Original position using power tools.			
		Gross Labour Cos	st (S\$)		1,540.00

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	80.00	0.00	80.00
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	0.00 1	45.00 ×
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	850.00	0.00	850.00 & 0{
		Waxing are also available. Gross Labou	r Cost (S\$)		975.00

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before after spray painting

- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and

Acknowledged by Repairer

p. 2537.1 2-1502.62 5.N-800 4-1560 431282