

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (5 lines) Fax: 6744 2368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : Sompso Insurance Singapore Pte Ltd
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623

TEL: FAX:
ATTN: Motor Claim Department
Your Ref No : 21/SP/OD-110 (03)
Claim Type : OD CLAIM
Accident Date : 25/02/2021

Claim No :
No :
Date : 11/03/2021
Policy No : D21MTPCVE000272
Veh Reg No : YN5910X
Make / Model : ISUZU NMR85UH5A
Chasis No : JAANMR85HE7101557
Engine No :
Reg. No :

ESTIMATE FOR VEHICLE NO: YN5910X

Discription	Quantity	List Price	Amount
Cost Price		S\$	S\$
1 FRT RH DOOR	1 PC	\$820.00 <i>bt</i>	
2 FRT RH DOOR OUTER HANDLE	1 PC	\$95.00 <i>gt</i>	
3 FRT RH DOOR SIGNAL LAMP	1 PC	\$115.00 <i>an</i>	
4 FRT RH DOOR STEP GARNISH	1 PC	\$165.00 <i>an</i>	
5 FRT RH DOOR LOWER HINGE	1 PC	\$95.00 <i>RY</i>	
6 FRT RH CORNER PANEL	1 PC	\$240.00 <i>an</i>	
7 FRT RH CORNER PANEL SIDE RUBBER	1 PC	\$75.00 <i>in</i>	
8 FRT RH CORNER PANEL TOP COVER	1 PC	\$95.00 <i>an</i>	
9 HEADLAMP RH	1 PC	\$350.00 <i>an</i>	
10 HEADLAMP LOWER RUBBER	1 PC	\$30.00 <i>in</i>	
11 FRT BUMPER	1 PC	\$400.00 <i>de</i>	
12 FRT BUMPER BRACKET RH	1 PC	\$150.00 ?	
13 FOG LAMP RH	1 PC	\$280.00 <i>an</i>	
14 SIDE MIRROR RH	1 PC	\$90.00 <i>cut</i>	
15 PETROL TANK BRACKET RH	1 PC	\$155.00 x ?	
16 TAIL LAMP LH	1 PC	\$65.00 <i>an</i>	
17 TAIL LAMP BRACKET LH	1 PC	\$45.00 ?	
18 REAR NUMBER PLATE BRACKET	2PCS	\$140.00 <i>mis</i>	
19 NUMBER PLATE LAMP	2PCS	\$110.00 <i>mis</i>	
20 AIR CLEANER BOX	1 PC	\$290.00 ?	
21 AIR FILTER	1 PC	\$145.00 ?	
22 FRT SIGNAL LAMP RH	1 PC	\$130.00 <i>cut</i>	
		\$4,080.00	
	Add 10%	\$408.00	\$4,488.00

Special Net

23 REAR NUMBER PLATE	1 PC	\$35.00 <i>mis</i>
24 REAR REINFORCEMENT BAR	1 PC	\$950.00 <i>bt - 750.</i>
25 REAR REINFORCEMENT BAR BRACKET LH	1 PC	\$250.00 ?
26 REAR SIDE ALUMINIUM FRAME LH	1 PC	\$850.00 <i>bt - 650.</i>
27 REAR WOODEN PLANK <i>SUPPORT</i>	2 PC	\$850.00 x 2 <i>cm - 700x2</i>
28 REAR WOODEN PLANK RUBBER SUPPORT LH	1 PC	\$180.00 <i>cut</i>
29 LH SIDE BOARD	1 PC	\$1,500.00 <i>bt - 1200.</i>
30 RH SIDE BOARD	1 PC	\$1,500.00 <i>bt - 1200.</i>
31 LH SIDE BOARD ALUMINIUM LOWER FRAME	1 PC	\$650.00 <i>bt - 450.</i>
32 RH SIDE BOARD ALUMINIUM LOWER FRAME	1 PC	\$650.00 <i>bt - 450.</i>
33 RH REINFORCEMENT BAR	1 PC	\$950.00 <i>bt - 750.</i>
34 ENGINE OIL	1 PC	\$150.00 ?
		\$9,365.00

Labour	
1	WIRE CHECKING
2	TRANSFER DOOR COMPONENT
3	LABOUR CHARGE
4	SPRAY PAINTING

\$30.00	✓
\$100.00	50
\$750.00	700
\$850.00	700
\$1,730.00	

Amount Before Excess	\$15,533.00
Less Excess	\$0.00
Amount Before GST	\$15,533.00
Add GST @7%	\$1,040.81
Total Amount Payable	\$16,623.81

For SME MOTOR PTE LTD

AUTHORISED SIGNATURE

Tanpin 17495749 / 62563561

'WP' Not Authorise

Revert Exp: to be advise

Tanpin @ 11/11/2011

0 7 days front panel

14 days - Rear box

P/P Resurvey new parts.
15/3/2012 3pm.

No 2nd hand parts for Rear box.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: