

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GB39078H

at Workshop m/s

752 01-44

of

Insured:

SJ56037J

Policy No.

Claims No.

CMTD>100797/LOR

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

26k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4
20

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

949D

Vehicle: IN / OUT

Date:

Person Contacted:

02766

Date / Time

Action / Instruction

cont'd 31-8-2025 LTA 10742

27/3/21 L/s 5000 cont'd with Eric. (Red 13,138.75, 72M)

Veh No:

GB39078H

Yr Regn:

Z/19/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

cm

Make:

Toyota hiace

c.c

2982

Colour

Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

337689

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT02P300060866

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

gre max

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/3/21

D.O.I.

16/3/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 29/3- typist

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Report Format:

TP

Lump Sum / I.B.I. (\$

5000p

Add Fee:

☐

Site Insp (\$

) ___ S + RS, ___ SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	949D

Vehicle Details

Vehicle No.:	GBB9078H
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Mar 2021
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	1KD2023577
Chassis No.:	JTFHT02P300060866
Maximum Power Output:	-
Open Market Value:	\$25,387.00
Original Registration Date:	07 Sep 2010
First Registration Date:	07 Sep 2010
Transfer Count:	0
Actual ARF Paid:	\$1,270.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 Aug 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$12,051.00
COE Rebate Amount:	\$10,742.00
Total Rebate Amount:	\$10,742.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 16 Mar 2021

OK

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2016 BMW 116d At \$75,800.



1 Owner, Low Mileage, Fully
Serviced By Agent.
Hamilton Autohub StarAd

HIN LUNG AUTO
HoBee Group
30 years of car sale
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

Browse by Category Sort by Date Posted 20 results/page

5 vehicles

Hiace 2025

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Hiace 2025		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Toyota Hiace 2.5M (COE till 07/2025)		\$27,800	\$6,460 /yr	05-Jul-2005	2,494 cc	-	Van	Available
	Fuel Type: Diesel Consignment Van, Coe 7/2025. Tax 7/2021 Posted: 16-Mar-2021 Tags: 2005 Toyota Hiace, Toyota Hiace, Toyota, Hiace								
	Toyota Hiace 3.0M (COE till 12/2025)		\$38,800	\$8,090 /yr	11-Feb-2011	2,982 cc	-	Van	Available
	Fuel Type: Diesel Rear-Aircon! Most Reliable Van In Town! No Repair Needed! Loan Up To 100%! In-House Warranty! High Trade-In! Call For Viewing Wit... SG Motor Link Pte Ltd Posted: 11-Mar-2021 Tags: 2011 Toyota Hiace, Toyota Hiace, Toyota, Hiace								
	Toyota Hiace 3.0M DX (COE till 04/2025)		\$31,800	\$7,730 /yr	27-Apr-2010	2,982 cc	-	Van	Available
	Fuel Type: Diesel 1 Owner Only. Good Condition! Well Maintained. Accident-Free. Still Can Renew Another 5 Years COE. Call Us For View Now. Posted: 08-Mar-2021 Tags: 2010 Toyota Hiace, Toyota Hiace, Toyota, Hiace								
	Toyota Hiace 3.0M (COE till 07/2025)		\$37,800	\$8,630 /yr	27-Sep-2010	2,982 cc	185,000 km	Van	Available
	Fuel Type: Diesel Exclusive 3-Months Warranty! 5 Doors Unit With Genuine Low Mileage! Previous Owner Spare Unit Seldom Use, Condition Maintained Ve... Car (S) Pte Ltd Posted: 01-Mar-2021 Tags: 2010 Toyota Hiace, Toyota Hiace, Toyota, Hiace								

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Hiace Commuter 3.0A High Roof (COE till 10/2025)

\$29,800

\$6,440 /yr

21-Feb-2011

2,982 cc

-

Bus

Available

Fuel Type: Diesel

Toyota Hiace Hi-Roof Excursion Bus! Tip Top Condition And Reliable, Well Serviced And Maintained, Low Depreciation, In House Loan Av...

Posted: 25-Feb-2021 Tags: 2011 Toyota Hiace, Toyota Hiace, Toyota, Hiace

TSL AUTO GARAGE

QUOTATION/ESTIMATE

RE: REPAIR VEHICLE ON TOYOTA HIACE

VEHICLE NO : GBB9078H

DATE : 15/03/2021

Not Adult
2/s \$5000
H days
Whipley
16/3/21

PARTS DESCRIPTION

LIST ITEMS

PARTS DESCRIPTION	QTY	UNTIL PRICE	AMOUNT
1 REAR TAILGATE <i>Body</i> <i>1956.20</i>	1	\$2,170.00	\$2,170.00 ✓
2 REAR TAILGATE LOCK <i>u 1</i>	1	\$340.00	\$340.00 X
3 REAR TAILGATE LOCK CATCH <i>u 1</i>	1	\$168.00	\$168.00 X
4 REAR TAILGATE HING LH <i>u 1</i>	1	\$134.00	\$134.00 X
5 REAR TAILGATE HING RH <i>u 1</i>	1	\$134.00	\$134.00 X
6 REAR BUMPER <i>D.S</i> <i>481.20</i>	1	\$679.00	\$679.00 ✓
7 REAR BUMPER BEAM <i>NS</i>	1	\$498.00	\$498.00 X
8 REAR BUMPER SIDE RETAINER LH <i>Ats</i> <i>79.10</i>	1	\$85.00	\$85.00 ✓
9 REAR BUMPER SIDE RETAINER RH <i>u 1</i>	1	\$85.00	\$85.00 X
10 REAR WEATHER STRIPE <i>TM</i> <i>299.20</i>	1	\$395.00	\$395.00 ✓
11 REAR TAILGATE STOPPER LH <i>u 1</i>	1	\$34.00	\$34.00 X
12 REAR TAILGATE STOPPER RH <i>u 1</i>	1	\$34.00	\$34.00 X
13 REAR TAILGATE LOGO <i>NZ</i>	1	\$65.00	\$65.00 X
14 REAR END PANEL INNER <i>B. 1500</i>	1	\$871.00	\$871.00 ✓
15 REAR END PANEL OUTER <i>B. 1500</i> <i>286.10</i>	1	\$597.00	\$597.00 ✓
16 REAR END PANEL TOP CHROME MOULDING <i>NZ</i>	1	\$115.00	\$115.00 X
17 LH REAR TAILLAMP LH <i>cm</i> <i>322.10</i>	1	\$478.00	\$478.00 ✓
18 LH REAR TAILLAMP PANEL LH <i>n</i>	1	\$589.00	\$589.00 X
19 LH REAR TAILLAMP LOWER APRON PANEL <i>ns</i> <i>101.29</i>	1	\$167.00	\$167.00 ✓
20 LH REAR TAILLAMP LOWER APRON PANEL BRACKET <i>u 1</i>	1	\$75.00	\$75.00 X
21 REAR SPARE TYRE LOCK NUT <i>u 1</i>	1	\$112.00	\$112.00 X
22 REAR SPARE TYRE BRACKET <i>u 1</i>	1	\$381.00	\$381.00 X
23 REAR FLOOR PANEL <i>n</i>	1	\$2,690.00	\$2,690.00 X
24 REAR WINDSCREEN GLASS MOULDING <i>NS</i>	1	\$189.00	\$189.00 X

TOTAL :
LESS 25 % :
TOTAL :

\$11,085.00	\$11,085.00
\$2,771.25	\$2,771.25
\$8,313.75	\$8,313.75

S/NETT ITEMS

1 REAR TAILGATE INNER TRIM PLATE <i>u 1</i>	1	\$950.00	\$950.00 X
2 REAR FLOOR PANEL TOP CHECKER PLATE <i>Back LR</i>	1	\$1,800.00	\$1,800.00 200
3 REAR WINDSCREEN GLASS SEALANT <i>u</i>	1	\$120.00	\$120.00 40
4 REAR END PANEL SEALANT <i>u</i>	2	\$120.00	\$120.00 50
5 REAR TAILGATE INNER TRIM PLATE RIVET (1 SET) <i>u</i>	1	\$150.00	\$150.00 50
6 REAR BUMPER CLIPS <i>u</i>	1	\$80.00	\$80.00 50
7 REAR TAILLAMP CLIPS <i>u 1</i>	2	\$12.00	\$24.00 X
8 REAR TAILLAMP LOWER APRON PANEL CLIPS <i>u 1</i>	±2	\$8.00	\$16.00 X
9 REAR REVERSE SENSOR <i>shorted</i>	1 set	\$250.00	\$250.00 200
10 REAR TAILGATE COMPANY STICKER <i>u</i>	1 set	\$450.00	\$450.00 280

11 70 KM/H STICKER <i>nel</i>	1	\$25.00	\$25.00 <i>10</i>
12 REAR FLOOR PANEL TOP CHECKER PLATE SEALANT <i>11</i>	1	\$80.00	\$80.00 <i>X</i>
13 LH REAR TAILLAMP PANEL SEALANT <i>11</i>	1	\$60.00	\$60.00 <i>X</i>
TOTAL :		<u>\$4,105.00</u>	<u>\$4,125.00</u>

TOTAL SPARE PARTS : \$12,418.75 \$12,438.75

LABOUR DESCRIPTION	AMOUNT
1 LABOUR FOR PANEL BEATING	\$1,600.00 <i>980</i>
2 LABOUR FOR SPRAYPAINTING	\$1,200.00 <i>600</i>
3 TO RUST PROOF ON REAR ACCIDENT AREAS	\$400.00 <i>2600</i>
4 TO APPLY TUFF COAT ON ACCIDENT AREAS	\$400.00 <i>100</i>
5 LABOUR FOR REMOVE AND REFIX REAR WINDSCREEN GLASS	\$150.00 <i>60</i>
6 LABOUR FOR REMOVE AND TRANSFER ALL REAR TAILGATE FITTING TO NEW	\$150.00 <i>52</i>
7 LABOUR FOR REMOVE AND RENEW REAR REVERSE SENSOR	\$120.00 <i>20</i>
8 WIRING CHECK	\$80.00 <i>11</i>
9 TEST FOR WATER LEAKING	\$100.00 <i>X</i>
10 LABOUR FOR REMOVE / RENEW REAR FLOOR PANEL CHECKER PLATE TO FACILIATE THE REPAIR REAR FLOOR PANEL	<i>11</i> \$1,500.00 <i>X</i>
TOTAL LABOUR :	<u>\$5,700.00</u>

TOTAL PARTS AND LABOUR : \$18,138.75

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-4676-10
252
P-3507-07
SW-880
L-1870
6257-07