

吉维利企业 **KIVILE ENTERPRISE**

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2533

EMAIL: KIVILEPC@GMAIL.COM

ROC NO.: 53114844X GST REG NO.: M90370110N

VEHICLE NO.: FU5315C

MAKE AND MODEL: WAVE 125

HANDLE GRIP	/ <i>IN</i>	30
HANDLE BAR	X <i>NN</i>	95
SIDE MIRROR	<i>cut</i>	38
IU	<i>cut</i>	156
IU HOLDER	X <i>NN</i>	30
FRONT FAIRING	X <i>NN</i>	125
SIDE FAIRING	<i>cut</i>	165
FOOTREST	<i>cut</i>	48
FORK REPAIR	X	180
FORK UNDER BRACKET	X	180
STEERING BEARING	X <i>NN</i>	95
FRONT RING	X	155
ALIGNMENT	X	250
LABOUR		250 <i>100</i>
tow	X <i>NN</i>	50

Total: 350.

*ATTN Officer Incharge,
 pls arrange survey to inspect my FU5315C, thanks*

*Irene
 153121*

*1 Day
 Insur repair
 After repair photos.*

*Eric Qiang
 8288 0282*

17/3/21.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: