

ASSIGNED BY: frl.

ALG

(2030)

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Bifrost Auto
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$76k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SIX 7175M (r Regn: 02 Jun 2010)
 Type: M.Cac / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Merce E250 cc 1796
 Colour: Red A/C: Insured / Std / NI / NA
 Sp Reading: 111499 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDD2074472.053132
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim STD A/Rim, or
 Tyre Size: F: 265/30ZR19
 R: L7
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 16-03-21
 Survey held at W/S 11:30
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Col: 7 30630
No Body Injuned.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Insp (\$)
☐ Disposal (\$)

Survey Fee:

Transportation:

3 + RS \$

Photos

Other:

Page:

Estimate for SJX7175M(Mercedes E250 Cab)

*BOOT LID	BT	\$2,150.00	✓
*BOOT LID BADGE	1/18C	\$60.00	40
*BOOT LID EMBLEM E250	X NN	\$68.00	48
*BOOT LID EMBLEM C&C	2/BR	\$40.00	
*REAR BUMPER	2/BR	\$1,425.00	1377
*REAR BUMPER LOWER SKIRT	X NN	\$726.00	384
*REAR BUMPER SIDE RETAINERS	NW	\$164.00	
*REAR BUMPER CLIPS	1/18C X 1/PC	\$50.00	✓
*REAR BUMPER REVERSE SENSOR	X	\$780.00	195
*REAR BUMPER REVERSE SENSOR HOLDERS	X NN	\$88.00	
*REAR BUMPER TOW COVER	X	\$32.00	
*REAR BUMPER REINFORCEMENT	2/BR	\$669.00	
*REAR BUMPER APRON GARNISH	2/BR	\$172.00	124.8
*REAR BUMPER SIDE CHROME MOULDING	1/4 EC	\$250.00	195.6
*REAR BUMPER CENTER CHROME MOULDING		\$186.00	97.8
*REAR BUMPER STAY	2/BR	\$36.00	✓
*END PANEL	X 1/18C	\$1,092.00	
*END PANEL TOP TRIM	2/BR	\$165.00	✓
*END PANEL TOP TRIM CLIPS	X NN	\$30.00	
*TAILLAMPS	X 1/18C, LH X NN	\$1,240.00	620
*TAILLAMPS INNER SEALER	X	\$76.00	
*TAILLAMP CLIPS	X NN	\$50.00	
Less 10%		\$9,549.00	5483.2
		\$954.90	
		\$8,594.10	4934.88
PANEL BEATING		\$1,400.00	400 600
SPRAY PAINTING		\$1,400.00	600
CHECK WIRING		\$50.00	30
ANTI RUST		\$100.00	X NN
REMOVE AND INSTALL CARPET AND SEAT		\$150.00	X 60
REMOVE AND INSTALL REVERSE SENSOR		\$90.00	40
REMOVE AND INSTALL REVERSE CAMERA		\$150.00	40
REMOVE AND INSTALL REAR EXHAUST SILENCER		\$120.00	X NN
TO REPROGRAM AND RESET SRS UNIT AND SENSOR		\$550.00	50
STICKER WRAPPING FOR DAMAGED PORTION	1/18C	\$1,000.00	7 500
		\$5,010.00	1920
Total		\$13,604.10	6854.88

-20%: 5500

Amo Qian
16/3/2021
6 Days
4/5
After repair photos.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: