

Christopher Yow Thiam Loong
14 Ang Mo Kio St 63
Block B
Singapore 569116

TP
Date 13/3/2021
No of Page : 1/1

Registration No : SLG 5090C

Model : Mitsubishi Lancer

Accident Date : 12-Mar-21

Chassis No: JMYSRCY1AGU004692

Our Ref : TP

Engine Capacity :

S/No	Qty	Items	Unit Price	Amount
1	1	Front Door RHS <i>KAR / DD</i>	\$ 921.50 -	\$ 921.50 -
2	1	Front Door Weatherstrip RHS <i>X</i>	\$ 198.00 -	\$ 198.00 -
3	1	Rear Door RHS <i>/ DD</i>	\$ 895.60 -	\$ 895.60 -
4	1	Rear Door Window Moulding RHS <i>/ Nec</i>	\$ 144.00 -	\$ 144.00 -
5	1 <i>blade</i>	Rear Door Frame RHS 7410A170XA <i>? / Nec</i>	\$ 55.00 -	\$ 55.00 -
6	1	Rear Door Weatherstrip RHS <i>/ CKY</i>	\$ 198.00 -	\$ 198.00 -
7	1	Rear Door Upper Hinge RHS <i>? / BT</i>	\$ 65.00 -	\$ 65.00 -
8	1	Rear Door Lower Hinge RHS <i>? / BT</i>	\$ 65.00 -	\$ 65.00 -
9	1	Rear Door Lock RHS <i>/ Jtm</i>	\$ 244.50 -	\$ 244.50 -
10	1	Rear Door Outer Handle RHS <i>X Svc</i>	\$ 122.00 -	\$ 122.00 -
11	1	Rear Door Electric Window Regulator RHS <i>? / BT</i>	\$ 265.00 -	\$ 265.00 -
12	1	Rear Door Window Motor RHS <i>? X</i>	\$ 251.00 -	\$ 251.00 -
13	1	Rear Door Water Shield RHS 7265A036 <i>? X</i>	\$ 55.00 -	\$ 55.00 -
14	1	Rear Door Trim RHS <i>? / CKY</i>	\$ 455.80 -	\$ 455.80 -
15	1	Rear Door Speaker RHS <i>? / CKY</i>	\$ 255.00 -	\$ 255.00 -
16	1	Rear Side Panel RHS 5301C346 <i>/ CKY</i>	\$ 785.20 -	\$ 785.20 -
17	1	Rear Fender Inner Shield RHS <i>X</i>	\$ 65.80 -	\$ 65.80 -
18	1	Rear Absorber set RHS <i>? X</i>	\$ 785.00 -	\$ 785.00 -
19	1	Rear Lower Arm RHS <i>? X</i>	\$ 328.00 -	\$ 328.00 -
20	1	Rear Wheel Bearing and Hub RHS <i>? / Jtm</i>	\$ 374.00 -	\$ 374.00 -
21	1	Rear Bumper <i>X</i>	\$ 785.60 -	\$ 785.60 -
22	1	Rear Bumper Retainer RHS <i>X</i>	\$ 28.00 -	\$ 28.00 -
23	1	Centre Door Pillar <i>X</i>	\$ 385.70	\$ 7,727.70 -
				-10% \$ 772.77 -
Total for spare parts				\$ 6,954.93 -

Special Nett

1	1 set	Door Hinge Clips <i>? X</i>	\$ 50.00	\$ 50.00
2	1 pc	Rear Rim RHS <i>/ SCK</i>	\$ 380.00	\$ 380.00
3	1 pc	Rear Tyre RHS <i>X</i>	\$ 180.00	\$ 180.00
Total for SP				\$ 610.00
Sub-Total for Parts :				\$ 610.00



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts		1,500.00 <i>1,200</i>
2		To putty and spray paint on all accident damage parts and other accident		1,500.00 <i>700</i>
3		Transfer of existing front door mechanism to new door		150.00 <i>60</i>
4		Transfer of existing rear door mechanism to new door		150.00 <i>60</i>
5		Wheel Alignment		80.00 <i>60</i>
6		To check wiring system to facilitate repair and refit the same		80.00 <i>30</i>
7		Apply rust proofing on the adjacent panels		80.00 <i>40</i>

TOTAL AMOUNT : 3,540.00
OVERALL COST : 11,104.93

Repair day 6 days

L15

After painting photo

Sun Pin(Lkk)

15/03/2024

TP within 30 days

Sunpin @ 1kkauto.com

8661 2627