



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction

14 Ang Mo Kio St.63, Block B (S) 569116
Tel : 6453 6279 / 6456 5410
Email : contact@kgcworkshop.com.sg

Christopher Yow Thiam Loong
14 Ang Mo Kio St 63
Block B
Singapore 569116

TP
Date 13/3/2021
No of Page : 1/1

Registration No : SLG 5090C

Model : Mitsubishi Lancer

Accident Date : 12-Mar-21

Chassis No: JMYSRCY1AGU004692

Our Ref : TP

Engine Capacity :

S/No	Qty	Items	Unit Price	Amount
1	1	Front Door RHS <i>Mar / PD</i>	\$ 921.50 -	\$ 921.50 ✓ -
2	1	Front Door Weatherstrip RHS <i>X SVC</i>	\$ 198.00 -	\$ 198.00 X -
3	1	Rear Door RHS <i>/ PD</i>	\$ 895.60 -	\$ 895.60 ✓ -
4	1	Rear Door Window Moulding RHS <i>/ Nec</i>	\$ 144.00 -	\$ 144.00 ✓ -
5	1 <i>blk</i>	Rear Door Frame RHS 7410A170XA <i>? / Nec</i>	\$ 55.00 -	\$ 55.00 ✓ -
6	1	Rear Door Weatherstrip RHS <i>/ Chy</i>	\$ 198.00 -	\$ 198.00 152 -
7	1	Rear Door Upper Hinge RHS <i>? / BT</i>	\$ 65.00 -	\$ 65.00 ✓ -
8	1	Rear Door Lower Hinge RHS <i>? / BT</i>	\$ 65.00 -	\$ 65.00 ✓ -
9	1	Rear Door Lock RHS <i>/ Jtm</i>	\$ 244.50 -	\$ 244.50 ✓ -
10	1	Rear Door Outer Handle RHS <i>X SVC</i>	\$ 122.00 -	\$ 122.00 X -
11	1	Rear Door Electric Window Regulator RHS <i>? / B\$</i>	\$ 265.00 -	\$ 265.00 ✓ -
12	1	Rear Door Window Motor RHS <i>? X SVC</i>	\$ 251.00 -	\$ 251.00 X -
13	1	Rear Door Water Shield RHS 7265A036 <i>? X SVC</i>	\$ 55.00 -	\$ 55.00 X -
14	1	Rear Door Trim RHS <i>? / Chy</i>	\$ 455.80 -	\$ 455.80 ✓ -
15	1	Rear Door Speaker RHS <i>? / Chy</i>	\$ 255.00 -	\$ 255.00 210 -
16	1	Rear Side Panel RHS 5301C346 <i>/ Chy</i>	\$ 785.20 -	\$ 785.20 ✓ -
17	1	Rear Fender Inner Shield RHS <i>X SVC</i>	\$ 65.80 -	\$ 65.80 X -
18	1	Rear Absorber set RHS <i>? X SVC</i>	\$ 785.00 -	\$ 785.00 X -
19	1	Rear Lower Arm RHS <i>? X SVC</i>	\$ 328.00 -	\$ 328.00 X -
20	1	Rear Wheel Bearing and Hub RHS <i>? / Jtm</i>	\$ 374.00 -	\$ 374.00 ✓ -
21	1	Rear Bumper <i>X SVC</i>	\$ 785.60 -	\$ 785.60 X -
22	1	Rear Bumper Retainer RHS <i>X SVC</i>	\$ 28.00 -	\$ 28.00 X -
23	1	Centre Door Pillar <i>X SVC</i>	\$ 385.70	\$ 7,727.70 - 4632.60
			-10% -10%	\$ 772.77 - -10%
Total for spare parts			\$	\$ 6,954.93 - 42169.34

Special Nett

1	1 set	Door Hinge Clips <i>? X SVC</i>	\$ 50.00	\$ 50.00 X
2	1 pc	Rear Rim RHS <i>/ Sck</i>	\$ 380.00	\$ 380.00 ✓
3	1 pc	Rear Tyre RHS <i>X SVC</i>	\$ 180.00	\$ 180.00 X
Total for SP			\$	\$ 610.00 380.
Sub-Total for Parts :			\$	\$ 610.00



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts		1,500.00 1,200 1,500
2		To putty and spray paint on all accident damage parts and other accident		1,500.00 700.
3		Transfer of existing front door mechanism to new door		150.00 60
4		Transfer of existing rear door mechanism to new door		150.00 60
5		Wheel Alignment		80.00 60
6		To check wiring system to facilitate repair and refit the same		80.00 30.
7		Apply rust proofing on the adjacent panels		80.00 40.

TOTAL AMOUNT : 3,540.00 2150
OVERALL COST : 11,104.93

Repair day 6 days

LIS

After prim photo

Sun Pin(Lkk)

15/03/2024

TP within program

Sunpin @ lkkauto.com

8661 2627

4,169.34

380

3150

6,699.34

- 20%

5,359.47

LIS

\$5,350

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: