

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD227Y**AAD2103-061***Not Notified**1/1 Sep & 7 Oct**Parts And Spry, Painting Of The Affected Portion*

Vehicle No.:

Chassis No.: *12 MAR 2021*Vehicle Make: *Part Remove And Renewal Of Parts*Vehicle Model: *Same The Same*

Date of Accident:

Third Party Insurer: *The Affected Areas*

Date of Registration:

SHD227Y

VF1ABL15AUC282165

RENAULT

LATITUDE

11/03/2021

AIG

16/10/2015

*To install rear bumper parking sensor***PART**

- 1 BUMPER COVER REAR *Wings attachments and*
- 1 BUMPER LOWER REAR *test*
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE RH REAR *plus*
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER BRACKET SIDE LH REAR *the same to repair*
- 1 BUMPER RETAINER LH REAR *pe*
- 1 BUMPER BEAM REAR
- 1 BUMPER BEAM BRACKET LH REAR *is attached and*
- 1 BUMPER BEAM BRACKET RH REAR

LIST

\$	<i>h</i>	561.70	<i>X</i>
\$	<i>nd/hy</i>	411.90	<i>✓</i>
\$	<i>h</i>	98.10	<i>X</i>
\$	<i>h</i>	82.10	
\$	<i>h</i>	59.80	
\$	<i>h</i>	80.80	
\$	<i>h</i>	54.20	
\$	<i>h</i>	547.80	
\$	<i>h</i>	114.50	
\$	<i>h</i>	114.50	
\$		2,125.40	
10% \$		212.54	
\$		1,912.86	

Special Nett

- 1SET PARKING AID *ing & anxiety and computer wheel*
- 1SET REAR BUMPER CLIP
- 1SET BUMPER BRACKET CTR CLIP
- 1SET BUMPER BRACKET SIDE CLIP RH RR
- 1SET BUMPER RETAINER RH CLIP RR
- 1SET BUMPER BRACKET SIDE CLIP LH RR *mod*
- 1SET BUMPER RETAINER CLIP LH RR
- 1SET BUMPER LOWER REAR CLIP

\$	<i>h</i>	700.00	<i>X</i>
\$	<i>nn</i>	66.00	
\$	<i>nn</i>	33.00	
\$	<i>nn</i>	10.00	
\$	<i>nn</i>	20.00	
\$	<i>nn</i>	10.00	
\$	<i>nn</i>	20.00	
\$	<i>nn</i>	66.00	<i>✓</i>

TOTAL \$ 925.00**TOTAL PARTS \$ 2,837.86****LABOUR**

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO/GST Reg. No. 201019626G

SHD227Y

AAD2103-061

Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 2201

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts, \$ 3,000.00 2001
Adjust And Realign The Same

To Rust-Proofing Of The Affected Areas. \$ 170.00 X

To reinstall rear bumper parking sensor. \$ 170.00 X

To transfer of bootlid fittings, attachments and
perform water seepage test. \$ 170.00 X

To repair and realign rear exhaust pipe. \$ 170.00 X

To drop rear exhaust box, renew the same, to repair
and realign centre exhaust pipe. \$ 170.00 XTo transfer of rear end panel fittings, attachment and
perform water seepage test. \$ 170.00 XTo transfer of rear windscreen fittings and conduct
water seepage test. \$ 170.00 XTo check steering geometry and computer wheel
alignment \$ 220.00 X

To Check Electrical Lighting Concerned. \$ 170.00 X

TOTAL \$ 7,580.00**Over All Total \$ 12,330.72****(LUMP SUM)
Repair Days**1 1/2 days
20 DAYSLKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: