

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD227Y****AAD2103-061***Not Notified*  
*11 Sep & 7 Oct*

Vehicle No.:

Chassis No.:

12 MAR 2021

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHD227Y**

VF1ABL15AUC282165

RENAULT

LATITUDE

11/03/2021

**AIG**

16/10/2015

**PART**

1 BUMPER COVER REAR  
 1 BUMPER LOWER REAR  
 1 BUMPER BRACKET CTR REAR  
 1 BUMPER BRACKET SIDE RH REAR  
 1 BUMPER RETAINER RH REAR  
 1 BUMPER BRACKET SIDE LH REAR  
 1 BUMPER RETAINER LH REAR  
 1 BUMPER BEAM REAR  
 1 BUMPER BEAM BRACKET LH REAR  
 1 BUMPER BEAM BRACKET RH REAR

**LIST**

\$	<i>n</i>	561.70	<i>X</i>
\$	<i>notified</i>	411.90	<i>✓</i>
\$	<i>rh</i>	98.10	<i>X</i>
\$	<i>rh</i>	82.10	
\$	<i>rh</i>	59.80	
\$	<i>rh</i>	80.80	
\$	<i>rh</i>	54.20	
\$	<i>n</i>	547.80	
\$	<i>n</i>	114.50	
\$	<i>n</i>	114.50	
\$		<b>2,125.40</b>	
10% \$		<b>212.54</b>	
\$		<b>1,912.86</b>	

**Special Nett**

1SET PARKING AID  
 1SET REAR BUMPER CLIP  
 1SET BUMPER BRACKET CTR CLIP  
 1SET BUMPER BRACKET SIDE CLIP RH RR  
 1SET BUMPER RETAINER RH CLIP RR  
 1SET BUMPER BRACKET SIDE CLIP LH RR  
 1SET BUMPER RETAINER CLIP LH RR  
 1SET BUMPER LOWER REAR CLIP

\$	<i>rh</i>	700.00	<i>X</i>
\$	<i>na</i>	66.00	
\$	<i>na</i>	33.00	
\$	<i>na</i>	10.00	
\$	<i>na</i>	20.00	
\$	<i>na</i>	10.00	
\$	<i>na</i>	20.00	
\$	<i>na</i>	66.00	<i>✓</i>
<b>TOTAL \$</b>		<b>925.00</b>	
<b>TOTAL PARTS \$</b>		<b>2,837.86</b>	

**LABOUR**

**Trans-cab Auto Services Pte Ltd****AAD2103-061**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD227Y**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	200
To Rust-Proofing Of The Affected Areas.	\$	170.00	nn X
To reinstall rear bumper parking sensor.	\$	170.00	6 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	6 X
To repair and realign rear exhaust pipe.	\$	170.00	6 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	6 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	6 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	6 X
To check steering geometry and computer wheel alignment	\$	220.00	6 X
To Check Electrical Lighting Concerned.	\$	170.00	6 X

**TOTAL \$ 7,580.00****Over All Total \$ 12,330.72****(LUMP SUM)  
Repair Days***1 1/2 days*  
**20 DAYS**