



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 8312C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEEP CUT / DEFORMED	1,698.20	1,392.00
1	FRONT BUMPER INNER SPONGE	SERVICEABLE	325.00	-
2	FRONT BUMPER SIDE RETAINER @\$98.60	O/S TORN	197.20	53.00
1	FRONT BUMPER FOG LAMP GARNISH	SERVICEABLE	78.60	-
1	FRONT BUMPER OUTER CHROME GARNISH	GRAZED	485.45	288.43
2	FRONT BUMPER PARKING SENSOR @\$310.50	SHORTED	621.00	258.00
1	BONNET (ALUMINIUM)	DENTED	2,580.00	1,565.00
2	FRONT SUPPORT PANEL	SERVICEABLE	952.89	-
1	FRONT SUPPORT PANEL TOP GARNISH	SERVICEABLE	345.00	-
2	FRONT FENDER RH (ALUMINIUM)	CRACKED	1,084.52	746.00
3	FRONT FENDER MOULDING	SERVICEABLE	298.20	-
2	FRONT FENDER INNER COWLING RH	SERVICEABLE	485.00	-
2	HEADLAMP RH (LED)	GRAZED	2,814.60	2,610.20
1	HEADLAMP LOWER BRACKET RH	SERVICEABLE	378.20	-
1	HEADLAMP PANEL RH	SERVICEABLE	510.50	-
	LESS 10% DISCOUNT		-1,285.44	-691.26
			11,568.92	6,221.37
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT RH FENDER SEALANT (SN)	SERVICEABLE	80.00	-
1	SET BONNET SEALANT (SN)	SERVICEABLE	80.00	-
			160.00	-
<u>LABOUR</u>				
	TO CHECK WIRING SYSTEM.		80.00	30.00
	TO RE-PROGRAMME AND RESET AFTER REPAIR.		200.00	80.00
	TO R&R FRONT BUMPER, FRONT RH FENDER, BONNET, SUPPORT PANEL AND OTHER ATTACHMENTS.		2,000.00	500.00
	TO PUTTY AND RESPRAY FRONT BUMPER, FRONT RH FENDERS, BONNET AND ACCIDENT AFFECTED AREA.		1,500.00	750.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RUSTPROOFING.	NOT NECESSARY	150.00	-
			3,930.00	1,360.00
GRAND TOTAL			15,658.92	7,581.37
RECOMMENDED COST OF REPAIRS				7,581.37

Report Ref No. CS3/SMO20008377/GKqf3e2-1

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.