



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21003418/T1Utd3n2	
			Date: 23/09/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 5410G		Veh. Inspected	SMG 5853G
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2100826/LOR		Excess (\$)	0.00
Assign From	GRACE TEO		Assign Date	16/03/2021
2. Vehicle Particulars & Condition				
Make & Model	BMW 740LI SR		c.c	2998
Engine No.	HIDDEN		Year of Reg.	2015
Chassis No.	WBA7E22000GD99721		Colour	GREY
Odometer	137951 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		275/40 R19	PIRELLI	6 mm
L/H Front Tyre		275/40 R19	PIRELLI	6 mm
R/H Rear Tyre		275/40 R19	PIRELLI	6 mm
L/H Rear Tyre		275/40 R19	PIRELLI	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/03/2021		Inspection Date	17/03/2021
Survey held at	56 LOYANG WAY # 04-04			
Repairer	AP AUTOMOTIVE SERVICES PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	