

Estimation

Date _____
 Vehicle SMG 5853 G
 Make/Model BMW 740Li
 Chassis No. WBA7E22000GD99721

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	BOOTLID OUTER <i>garnish</i> the <i>replaced</i>	1	\$ 233.45	\$ 233.45
2	REAR BOOT KICK SENSOR WIRE HARNESS <i>cut</i>	1	\$ 46.55	\$ 46.55
3	REAR REINFORCEMENT BAR BRACKET <i>btw</i>	1	\$ 82.60	\$ 82.60
4	<i>REAR KICK</i> SENSOR <i>CIRCUIT</i> <i>499.50</i> <i>eng</i> <i>control unit</i>	1	Total	\$ 862.10 362.60
			Less 10%	\$ 36.26
			Total	\$ 775.89 326.34

628.65
 5/- 597.22

16378.05
 90
 1990
 597.22

 19055.27
 1/5 \$ 15,200
 7days #