



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21003420/Utd3n2	
			Date: 12/04/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBC 1887L	Veh. Inspected	SMY 2353H
	Policy No.	D20MTHCVE001720	Coverage (\$)	0.00
	Claim No.	CMTD2100812/MYE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	16/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FIT 1.3 (A)	c.c	1317
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	GR11002831	Colour	BROWN
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	BRIDGESTONE	9 mm
	L/H Front Tyre	185/60 R15	BRIDGESTONE	9 mm
	R/H Rear Tyre	185/60 R15	BRIDGESTONE	9 mm
	L/H Rear Tyre	185/60 R15	BRIDGESTONE	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/03/2021	Inspection Date	16/03/2021
	Survey held at	8 KAKI BUKIT AVE 4 # 05-23 PREMIER		
	Repairer	XIN YUN AUTO PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	