



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE HO			Ref: CC4/ASM21003422/Qba3q2 Date: 19/10/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 5783E	Veh. Inspected	SLM 4941Y	
Policy No.	P2418407	Coverage (\$)	0.00	
Claim No.	S1M03GVU	Excess (\$)	0.00	
Assign From		Assign Date	16/03/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SUBARU FORESTER 2.0L	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JF1SJ5KC5HG087357	Colour	WHITE	
Odometer	65863 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/60 R17	YOKOHAMA	6 mm	
L/H Front Tyre	225/60 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	27/02/2021	Inspection Date	16/03/2021	
Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>5 Working Days</b>	