

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8202 L/P: 9742, 6103

REPAIR ESTIMATE FOR SLM4941Y

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

No.	Qty	List Items		
1	1	Rear bumper / CRU	\$	580.30 /
2	1	Rear bumper LH reflector ? / CRA	\$	22.80 /
3	2	Rear bumper side retainer / BK	\$	36.00 /
4	1	Rear bumper inner reinforcement ? / BT	\$	388.00 /
5	1 set	Rear bumper clips / NEC	\$	40.00 /
6	1	LH taillamp / SCR	\$	432.00 /
7	1	Rear tailgate X R	\$	1,072.80 X
8	1	Rear tailgate centre top "SUBARU" logo / NEC	\$	98.00 /
9	1	Rear tailgate LH "SUBARU" emblem / NEC	\$	82.00 /
10	1	Rear tailgate RH "FORESTER" emblem / NEC	\$	72.00 /
11	1	Rear tailgate top lock X SVC	\$	186.40 X
12	1	Rear tailgate weatherstrip ? / BK	\$	120.00 /
13	1 set	Rear tailgate inner trim board clips X SVC	\$	60.00 X
14	1	Rear end panel ? / CRU	\$	368.00 /
15	1	Rear end panel top garnish ? / CRU	\$	140.00 /
16	1	Rear spare tyre panel / PD	\$	543.00 /
			\$	4,241.30 2,922.10
Less 20%			\$	848.26 - 20%
Total :			\$	3,393.04 2,337.68

Special Nett Items

17	1	Rear reverse sensors / SHOR	\$	250.00 200
18	1	Rear windscreen sealant X NN	\$	50.00 X
Total :			\$	300.00 200

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	1,200.00	600
2	To putty and spray Spray Paintings charges.	\$	1,000.00	800
3	To remove, refix rear windscreen.	\$	140.00	X
4	To remove, refix rear upholstery and attachments.	\$	120.00	60
5	To remove, refix rear tailgate fittings.	\$	80.00	X
6	To supply and apply anti rust treatment	\$	80.00	40
Total :		\$	2,620.00	1,500

Repair day - 5 days

Total Parts and Labour : \$ 6,313.04

LIS
After pain photo
Sun Pin (LKK)
16/03/2021
8661 2627
sunpin@lkkauto.com

2,337.68
200
1,500
4,037.68
- 20%
3,230.14

LIS
\$ 3,250
5 days