

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LAI YEW SENG PTE LTD
 7 TOA PAYOH LOR 8 #01-1247
 TOA PAYOH INDUSTRIAL PARK
 SINGAPORE 319059
 TEL: 62549851
 ATTN:

Estimate No: MC1901819
 Date: 12 Mar 2021
 Policy No: M0008313
 Veh Reg No: GBE116A
 Make/Model: NISSAN CABSTAR 3.0
 5M/T ABS 2DR 2WD
 EURO 5

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 10/03/2021
 TP Veh Reg No: GX1685H

Not Authorised
11 Days &
Repair After Paint
7 days

Estimate Repair Cost to Vehicle No :GBE116A

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 FRONT WINDSCREEN MOULDING TOP LH & RH	2 PC	216.00	99
2 FRONT WINDSCREEN MOULDING LH & RH	2 PC	176.00	99
3 FRONT WINDSCREEN MOULDING BOTTOM	1 PC	41.60	X nn
4 WIPER PANEL	1 PC	525.50	275
5 FRONT PANEL	1 PC	1,580.90	660
6 FRONT PANEL LOGO CABSTAR	1 PC	46.00	33
7 FRONT GRILLE	1 PC	670.60	264
8 FRONT GRILLE EMBLEM	1 PC	64.00	X
9 FRONT GRILLE CLIP	6 PC	30.60	X
10 FRONT GRILLE CENTRE BRACKET	1 PC	42.00	X
11 HEADLAMP LH & RH	2 PC	1,037.00	264
12 HEADLAMP LOWER COVER LH & RH	2 PC	178.00	60.50
13 FRONT BUMPER (WITH REINFORCEMENT)	1 PC	1,155.10	495
14 FRONT BUMPER BRACKET LH & RH	2 PC	122.00	41.80
15 REAR GATE ASSEMBLY	1 PC	1,459.60	715
16 REAR GATE STICKER NISSAN	1 PC	80.10	44
17 TAILAMP LH & RH	2 PC	532.60	154
		7,957.60	
	Less 10%	795.76	7,161.84
18 AIR CON CONDENSER BLOWER MOTOR	1 PC	587.00	X
19 AIR CON CONDENSER HEATER UNIT (WITH COOLING COIL)	1 PC	1,376.10	X
		1,963.10	1,963.10
Special Nett			
20 INNER SEAL	1 PC	20.00	—
21 SEALANT	1 PC	40.00	—
22 ERP SEALANT	1 PC	15.00	X
23 FRONT DOOR LH COMPANY REG. STICKER -CHECK PRICE	1 PC	0.0000	X
24 FRONT DOOR LH COMPANY STICKER LYS -CHECK PRICE	1 PC	0.0000	X
25 REAR GATE STICKER 70KM/H -CHECK PRICE	1 PC	0.0000	3.00
26 REAR GATE STICKER 13 PAX -CHECK PRICE	1 PC	0.0000	—
27 REAR GATE PLATE -CHECK PRICE	1 PC	0.0000	X
28 REAR GATE PLATE RIVET -CHECK PRICE	22 PC	0.0000	44
29 NUMBER PLATE	2 PC	70.00	40.00
30 NUMBER PLATE REAR REINFORCEMENT BAR	1 PC	0.0000	X
31 REVERSE SENSOR SET	1 PC	200.00	2

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LAI YEW SENG PTE LTD
7 TOA PAYOH LOR 8 #01-1247
TOA PAYOH INDUSTRIAL PARK
SINGAPORE 319059
TEL: 62549851
ATTN:

Estimate No: MC1901819
Date: 12 Mar 2021
Policy No: M0008313
Veh Reg No: GBE116A
Make/Model: NISSAN CABSTAR 3.0
5M/T ABS 2DR 2WD
EURO 5

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/03/2021
TP Veh Reg No: GX1685H

Estimate Repair Cost to Vehicle No :GBE116A

Description	Quantity	List Price S\$	Amount S\$
		345.00	345.00
LABOUR			
32 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	✓
33 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	✓
34 LABOUR TO REMOVE & REFIT FRONT WINDSCREEN	1 EA	120.00	✓
35 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.	1 PC	300.00	250/
36 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES. FRONT	1 PC	60.00	✓
37 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	✓
38 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD WIPER PANEL, FRONT PANEL. TO KNOCK & REPAIR FRONT DOOR LH, CORNER PANEL LH & RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	✓
39 TO SPRAY WIPER PANEL, FRONT PANEL, CORNER PANEL LH & RH, FRONT DOOR LH	1 PC	800.00	720/
		2,280.00	2,280.00
	Total		S\$ 11,749.94
	Add GST @ 7%		822.50
	Total Amount Payable		S\$ 12,572.44

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND FIVE HUNDRED SEVENTY TWO AND CENTS FORTY FOUR ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LAI YEW SENG PTE LTD
7 TOA PAYOH LOR 8 #01-1247
TOA PAYOH INDUSTRIAL PARK
SINGAPORE 319059
TEL: 62549851
ATTN:

Estimate No: MC1901819
Date: 17 May 2021
Policy No: M0008313
Veh Reg No: GBE116A
Make/Model: NISSAN CABSTAR 3.0
5M/T ABS 2DR 2WD
EURO 5

Your Ref No: -
Claim Type: Own Damage/Third Party
Accident Date: 10/03/2021
TP Veh Reg No: GX1685H

Estimate Repair Cost to Vehicle No :GBE116A

Description	Quantity	List Price S\$	Amount S\$
Supplementary Parts to Repair			
LABOUR			
1 TO REPAIR REAR END PANEL	1 PC	150.00	✓
2 TO SPRAY REAR GATE AND REAR END PANEL	1 PC	250.00	✓
		400.00	400.00
		Total	S\$ 400.00
		GST Amount	S\$ 28.00
		Total Amount Payable	S\$ 428.00

The above vehicle was surveyed by KENNETH KONG -LKK on 17/03/2021

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE