

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JFISJSKC5JG101390

TAN NANCY

BLK 229 JURONG EAST STREET 21

#06-715

S 600229

TPMS16

Xiao Chen

Vehicle No

Make/Model

Accident date

:SLU 8296 H

:SUBARU FORESTER

:15.03.2021

No	DESCRIPTION	Qty	Amount (\$\$)
----	-------------	-----	---------------

List Items

1	Front bumper <i>dehd</i>	1	\$ 660.00 ✓
2	Front bumper side holder @ \$26.40 <i>RH end</i>	2	\$ 52.80 <i>26.40</i>
3	Front bumper top RH side garnish <i>from</i>	1	\$ 26.40 ✗
4	Front bumper RH lower garnish	1	\$ 26.40 ✗
5	Front bumper RH fod lamp rim <i>crack</i>	1	\$ 47.50 ✓
6	Front bumper RH fod lamp <i>cracked</i>	1	\$ 467.50 <i>270</i>
7	Front bumper lower lip <i>dehd</i>	1	\$ 1,100.00 <i>600(SN)</i>
8	Front bumper reinforcement <i>new</i>	1	\$ 316.80 ✗
9	Front RH fender <i>Buckle</i>	1	\$ 297.60 ✓
10	Front RH fender inner shield <i>dehd</i>	1	\$ 118.80 ✓
11	Front RH headlamp <i>at</i>	1	\$ 2,617.60 <i>2400</i>
12	Front RH headlamp lower bracket <i>cracked</i>	1	\$ 39.60 ✗
13	Front grille <i>new</i>	1	\$ 380.20 ✗
14	Front support panel <i>Repair</i>	1	\$ 480.70 ✗
15	Front RH lower arm <i>Bent</i>	1	\$ 602.80 <i>558</i>
16	Front RH shock absorber <i>Bent</i>	1	\$ 400.00 ✓
17	Front RH drive shaft <i>new</i>	1	\$ 864.50 ✗
18	Front RH knuckle arm <i>end</i>	1	\$ 377.30 ✓
19	Front RH knuckle arm bearing <i>end</i>	1	\$ 297.00 ✓
20	Front RH linkage <i>bracket</i> <i>Bent</i>	1	\$ 110.50 ✓
21	Front RH support arm <i>new</i>	1	\$ 591.80 ✗
22	Front engine lower cover <i>new</i>	1	\$ 190.10 ✗
23	Steering rack assy <i>Bent</i>	1	\$ 2,799.70 <i>2520</i>
			\$ 12,865.60
Less 20% Disc			\$ 2,573.12
Total			\$ 10,292.48

Special Nett Items

1	Front bumper clips (1 set) <i>new</i>	\$ 60.00 <i>30</i>
2	Front RH fender inner shield clips (1 set) <i>new</i>	\$ 60.00 <i>30</i>
3	Front RH sport rim <i>at</i>	\$ 1,650.00 <i>500</i>
4	Front RH tyre <i>new</i>	\$ 380.00 ✗
Total		\$ 2,150.00

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TAN NANCY
BLK 229 JURONG EAST STREET 21
#06-715
S 600229

Vehicle No :SLU 8296 H
Make/Model :SUBARU FORESTER
Accident date :15.03.2021

No	DESCRIPTION	Qty	Amount (S\$)
----	-------------	-----	--------------

Labour Cost

1 Towing fee	\$	150.00	120
2 To check wheel alignment	\$	100.00	80
3 Remove & reinstall aircond fill in gas	\$	150.00	x
4 Remove & reinstall front suspension	\$	600.00	320
5 Remove ,replace & repair consistent to the accident	\$	1,500.00	600
6 Respray painting	\$	1,300.00	600
7 Tuff kote	\$	100.00	50
Total	\$	3,900.00	

Grand Total \$ 16,342.48

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Wheel: 9428.16

L/S: 7.5K.

07 Days

850

07 Days