

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0211/2021/HR
DATE : 15-Mar-21
WIP : 19249

VEHICLE NOT IN WORKSHOP. SURVEY ON 16/03/2021 @ 10AM

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS ANG POH LI
ADDRESS : 50 GOLDHILL AVENUE
#03-03
SINGAPORE 309031
TELEPHONE : HP +65 96430576
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800112182
VEHICLE NO : **SME 2864 E**
MODEL CODE : A3 SPORTSBACK 1.4 TFSI S TRONIC
MODEL YEAR : 25/9/2018
ENGINE NO : CZC 697609
CHASSIS NO : WAUZZZ8VXJA129745
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Mar-21
PLACE OF ACCIDENT : MOUNT ROSIE RD X MALCOM RD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SME 2864 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	? ✓ <i>lls.</i>
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,200.00	<i>lls.</i> 1200 ✓
3	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	250 ✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	6,300.00	1520 2750 <i>lls.</i>
5	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER. <i>Bonnet ✓</i>	\$	3,000.00	1650 <i>H20</i> ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 11,402.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SME 2864 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>could.</i>	1	\$ 2,016.00	✓ 1612.80
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 187.00	+
3	FRONT BUMPER GUIDE SECTION - RH <i>Not Nee</i>	1	\$ 39.00	✗
4	FRONT BUMPER LOWER GRILLE - CENTER <i>could</i>	1	\$ 160.00	✓ 128.00
5	FRONT BUMPER LOWER COVER - RH / CTR <i>Not Nee</i>	1	\$ 594.00	✗
6	FRONT RADIATOR OUTER GRILLE <i>could</i>	1	\$ 1,406.00	✓ 1124.80
7	FRONT RADIATOR END PLATE <i>could</i>	1	\$ 191.00	✓ 152.40
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>at del</i>	1	\$ 188.00	✓ 152.80
9	FRONT BUMPER FOAM FILLER PIECE <i>could</i>	1	\$ 189.00	✓ 151.20
10	FRONT BUMPER COVER <i>Reinforcement new</i>	1	\$ 795.00	✗
11	FRONT BUMPER COVER <i>could</i>	1	\$ 122.00	✓ 97.20
12	LOW TONE HORN - RH <i>Not Nee</i>	1	\$ 200.00	✗
13	FRONT FENDER - RH <i>could</i>	1	\$ 851.00	✓ 680.40
14	FRONT FENDER POP RIVERT <i>not ne</i>	8	\$ 27.00	✗
15	ATTACHMENT PARTS FOR FRONT FENDER - RH <i>new</i>	1	\$ 72.00	+
16	FRONT FENDER CENTER BRACKET - RH <i>Not Nee</i>	1	\$ 48.00	+
17	FRONT FENDER REAR BRACKET - RH <i>Not Nee</i>	1	\$ 28.00	+
18	FRONT FENDER BRACE <i>Not Nee</i>	1	\$ 96.00	✗
19	FRONT FENDER CLOSING ELEMENT <i>new</i>	1	\$ 62.00	+
20	FRONT WHEEL HOUSING LINER <i>new</i>	1	\$ 169.00	+
TOTAL SPARE PARTS		:	\$ 7,440.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SME 2864 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>Not</i>	1	\$ 57.00	+
22	FRONT BONNET <i>Dented</i>	1	\$ 2,745.00	✓ 2196
23	ATTACHMENT PARTS FOR BONNET <i>Not</i>	1	\$ 165.00	+
24	FRONT BONNET LID HINGE - LH / RH <i>Not</i>	2	\$ 124.00	+
25	FRONT BONNET EDGE PROTECTION <i>Not</i>	1	\$ 28.00	✓ 22
26	FRONT BONNET CATCH HOOK <i>Not</i>	1	\$ 90.00	+
27	FRONT BONNET STRIKER - LH / RH <i>Not</i>	1	\$ 220.00	+
28	FRONT BONNET CATCH HOOK <i>Not</i>	1	\$ 63.00	+
29	FRONT BONNET LOCK W/ MICRO SWITCH	2	\$ 427.00	+
30	FRONT BONNET BOWDEN CABLE	1	\$ 58.00	+
31	FRONT BONNET RELEASE CABLE COVER	1	\$ 10.00	+
32	FRONT BONNET SOUND INSULATOR	1	\$ 219.00	+
33	LED HEADLIGHT - RH <i>cracked</i>	1	\$ 5,455.00	✓ 4364.00
34	LED HEADLIGHT LIFT CYLINDER - RH <i>Not</i>	1	\$ 142.00	+
35	LED HEADLIGHT LIFT CYLINDER HOSE <i>Not</i>	1	\$ 68.00	+
36	FRONT RADIATOR LOCK CARRIER <i>cracked</i>	1	\$ 727.00	✓ 531.60
37	A/C CONDENSER W FLUID RESERVOIR	1	\$ 589.00	+
38	FRONT RADIATOR TEMP SENSOR BRACKET	1	\$ 19.00	+
39	FRONT RADIATOR - ADDITIONAL	1	\$ 859.00	+
40	FRONT RADIATOR	1	\$ 951.00	+
TOTAL SPARE PARTS		:	\$ 13,016.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SME 2864 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	COOLANT FOR RADIATOR 16L 16L	1	\$ 95.00	✓ 75.52
42	FRONT RADIATOR AIR GUIDE - RH cracked	1	\$ 25.00	✓ 19.44
43	FRONT RADIATOR OUTER AIR GUIDE SEAL - RH new	1	\$ 8.00	✓
44	FRONT RADIATOR UPPER AIR GUIDE SEAL - CENTER new	1	\$ 12.00	✓
45	FRONT NUMBER PLATE Dented	S/N	\$ 60.00	✓ 60.00
46	SUNDRIES New.		\$ 300.00	? 37.68
TOTAL SPARE PARTS		:	\$ 20,956.00	
TOTAL LABOUR CHARGES		:	\$ 11,402.00	
GRAND TOTAL		:	\$ 32,358.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Adrian Ling
16/03/21 ✓

Not Authorised, 06 Days.
09 Days. H.S.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: