



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SME 2864 E

Denise.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	?
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	✓
3	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,300.00	1500. +1250.
5	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 3,000.00	1100
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 11,402.00	

Car-in

25/3/21-

Wip: 19249

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Adnan

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SME 2864 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>could</i>	1	\$ 2,016.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 187.00	+
3	FRONT BUMPER GUIDE SECTION - RH	1	\$ 39.00	?
4	FRONT BUMPER LOWER GRILLE - CENTER <i>could</i>	1	\$ 160.00	✓
5	FRONT BUMPER LOWER COVER - RH / CTR	1	\$ 594.00	?
6	FRONT RADIATOR OUTER GRILLE <i>could</i>	1	\$ 1,406.00	✓
7	FRONT RADIATOR END PLATE <i>could</i>	1	\$ 191.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>at old</i>	1	\$ 188.00	✓
9	FRONT BUMPER FOAM FILLER PIECE <i>could</i>	1	\$ 189.00	✓
10	FRONT BUMPER COVER: Reinforcement	1	\$ 795.00	?
11	FRONT BUMPER COVER - foam filler piece <i>could</i>	1	\$ 122.00	✓
12	LOW TONE HORN - RH	1	\$ 200.00	?
13	FRONT FENDER - RH <i>Replaced</i>	1	\$ 851.00	✓
14	FRONT FENDER POP RIVERT <i>new</i>	8	\$ 27.00	✓
15	ATTACHMENT PARTS FOR FRONT FENDER - RH <i>new</i>	1	\$ 72.00	+
16	FRONT FENDER CENTER BRACKET - RH	1	\$ 48.00	+
17	FRONT FENDER REAR BRACKET - RH <i>new</i>	1	\$ 28.00	+
18	FRONT FENDER BRACE	1	\$ 96.00	?
19	FRONT FENDER CLOSING ELEMENT <i>new</i>	1	\$ 62.00	+
20	FRONT WHEEL HOUSING LINER <i>new</i>	1	\$ 169.00	+
TOTAL SPARE PARTS		:	\$ 7,440.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SME 2864 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>Not</i>	1	\$ 57.00	<i>x</i>
22	FRONT BONNET <i>Dented</i>	1	\$ 2,745.00	<i>x</i>
23	ATTACHMENT PARTS FOR BONNET <i>Not</i>	1	\$ 165.00	<i>x</i>
24	FRONT BONNET LID HINGE - LH / RH <i>Not</i>	2	\$ 124.00	<i>x</i>
25	FRONT BONNET EDGE PROTECTION <i>Not</i>	1	\$ 28.00	<i>x</i>
26	FRONT BONNET CATCH HOOK <i>Not</i>	1	\$ 90.00	<i>x</i>
27	FRONT BONNET STRIKER - LH / RH <i>Not</i>	1	\$ 220.00	<i>x</i>
28	FRONT BONNET CATCH HOOK <i>Not</i>	1	\$ 63.00	<i>x</i>
29	FRONT BONNET LOCK W/ MICRO SWITCH	2	\$ 427.00	<i>x</i>
30	FRONT BONNET BOWDEN CABLE	1	\$ 58.00	<i>x</i>
31	FRONT BONNET RELEASE CABLE COVER	1	\$ 10.00	<i>x</i>
32	FRONT BONNET SOUND INSULATOR	1	\$ 219.00	<i>x</i>
33	LED HEADLIGHT - RH <i>cracked</i>	1	\$ 5,455.00	<i>x</i>
34	LED HEADLIGHT LIFT CYLINDER - RH	1	\$ 142.00	<i>x</i>
35	LED HEADLIGHT LIFT CYLINDER HOSE <i>Not</i>	1	\$ 68.00	<i>x</i>
36	FRONT RADIATOR LOCK CARRIER <i>Not</i>	1	\$ 727.00	<i>x</i>
37	A/C CONDENSER W FLUID RESERVOIR	1	\$ 589.00	<i>x</i>
38	FRONT RADIATOR TEMP SENSOR BRACKET	1	\$ 19.00	<i>x</i>
39	FRONT RADIATOR - ADDITIONAL	1	\$ 859.00	<i>x</i>
40	FRONT RADIATOR	1	\$ 951.00	<i>x</i>
TOTAL SPARE PARTS		:	\$ 13,016.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SME 2864 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	COOLANT FOR RADIATOR <i>Not Also New</i>	1	\$ 95.00	☒
42	FRONT RADIATOR AIR GUIDE - RH <i>crushed</i>	1	\$ 25.00	☒
43	FRONT RADIATOR OUTER AIR GUIDE SEAL - RH ?	1	\$ 8.00	?
44	FRONT RADIATOR UPPER AIR GUIDE SEAL - CENTER ?	1	\$ 12.00	?
45	FRONT NUMBER PLATE <i>Dented</i>	S/N	\$ 60.00	☒
46	SUNDRIES ?		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 20,956.00	
TOTAL LABOUR CHARGES		:	\$ 11,402.00	
GRAND TOTAL		:	\$ 32,358.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

*Resurvey
Admin
26/03/21*

Add 3 days of repairs.