

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD CS3/ASM21003430/Gqf3e2 Ref: 8 SHENTON WAY #24-01 AXA Date: 05/04/2021 **TOWERSINGAPORE 068811** ATTN: TAN JUN HONG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. GBK 6461G SHD 6624U Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. S1M035CK Excess (\$) 0.00 TAN JUN HONG **Assign Date** 15/03/2021 Assign From **Vehicle Particulars & Condition** 2. NISSAN NV350 Make & Model 1998 C.C HIDDEN 2020 Year of Reg. Engine No. VR2E26126942 WHITE Chassis No. Colour Odometer 11458 KM Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/80 R15 YOKOHAMA 6 mm YOKOHAMA L/H Front Tyre 195/80 R15 6 mm 195/80 R15 YOKOHAMA R/H Rear Tyre 6 mm YOKOHAMA L/H Rear Tyre 195/80 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. 5. **General Information** 08/01/2021 16/03/2021 (05:45 PM) Inspect Date / Time Accident Date LENG WANG MOTOR Survey held at BLK 3007 UBI ROAD #01-414 SINGAPORE 408701 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000 5b. **Estimate Days of Repair ESTIMATED NORMAL PERIOD FOR REPAIR:** 2 Working Days

Report Ref No. CS3/ASM21003430/Gqf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.