

# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM\_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

AlG

Adrian LLC

15/03/2021

Blk 1 Kaki Bukit Ave 6  
# 01-43  
Singapore 417883

TPALG.  
Jaslin.

Accident date: 13/03/2021

Estimated repair cost for vehicle no: SJN4210S TOYOTA ALTIS 1.6 A '09

Chassis: MR053ZEE106140142

| S/N | QTY | ITEMS                             | U/PRICE  | AMOUNT     |
|-----|-----|-----------------------------------|----------|------------|
| 1   | 1   | Front Bonnet                      |          | \$481.85   |
| 2   | 2   | Front Bonnet Hinge                | \$121.35 | \$242.70   |
| 3   | 1   | Front Bonnet Lock                 |          | \$182.10   |
| 4   | 1   | Front Bonnet Insulator            |          | \$374.50   |
| 5   | 1   | Front Grille                      |          | \$381.10   |
| 6   | 1   | Front Bumper                      |          | \$561.85   |
| 7   | 10  | Front Bumper Clip                 | \$6.50   | \$65.00    |
| 8   | 1   | Front Bumper Emblem Logo          |          | \$61.75    |
| 9   | 1   | Front Bumper Top Rubber           |          | \$191.60   |
| 10  | 1   | Front Bumper Centre Lower Garnish |          | \$182.20   |
| 11  | 1   | Front Bumper Reinforcement        |          | \$374.40   |
| 12  | 1   | Front L/H Bumper Side Retainer    |          | \$122.10   |
| 13  | 1   | Front L/H Bumper Fog Lamp         |          | \$374.10   |
| 14  | 1   | Front L/H Bumper Fog Lamp Cover   |          | \$174.40   |
| 15  | 1   | Front L/H Head Lamp               |          | \$378.85   |
| 16  | 1   | Front L/H Fender                  |          | \$374.10   |
| 17  | 1   | Front L/H Fender Cowling          |          | \$182.10   |
| 18  | 10  | Front L/H Fender Cowling Clip     | \$6.50   | \$65.00    |
| 19  | 1   | Front L/H Rim                     |          | \$680.00   |
| 20  | 1   | Front L/H Tyre                    |          | \$350.00   |
| 21  | 1   | Front L/H Lower Arm               |          | \$581.90   |
| 22  | 1   | Front L/H Knuckle Arm             |          | \$561.60   |
| 23  | 1   | Front L/H Knuckle Arm Bearing     |          | \$191.80   |
| 24  | 1   | Front L/H Shock Absorber          |          | \$381.90   |
| 25  | 1   | Front L/H Drive Shaft             |          | \$1,712.40 |
| 26  | 1   | Front Steering Rack               |          | \$1,822.50 |

3413.45

Subtotal:- \$11,051.80

2560.08. S.N: 450

## Labour charges

|                                                           |                 |
|-----------------------------------------------------------|-----------------|
| To remove & refit front L/H undercarriage & steering rack | \$380.00 220.   |
| To check wheel alignment                                  | \$150.00 80     |
| To check wiring                                           | \$100.00 30.    |
| Tuff kote                                                 | \$150.00 50.    |
| Towing fee                                                | \$150.00 x.     |
| Panel beating                                             | \$1,000.00 500  |
| Spray painting                                            | \$1,200.00 400. |
|                                                           | 1280            |
| Subtotal:-                                                | \$3,130.00      |
| Total:-                                                   | \$14,181.80     |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L  
L/S 15/03/21

05 days

Supplementary: 322.12

total: 4612.20

L/S: 3.7K

3.7K

# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM\_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

15/03/2021

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

Accident date: 13/03/2021

Supplementary repair cost for vehicle no: SJN4210S TOYOTA ALTIS 1.6 A '09

Chassis: MR053ZEE106140142

| S/N | QTY | ITEMS                             | U/PRICE | AMOUNT   |
|-----|-----|-----------------------------------|---------|----------|
| 1   | 1   | Front Grille Assy                 |         | \$559.30 |
| 2   | 8   | Front Grille Clip                 | \$6.50  | \$52.00  |
| 3   | 1   | Front Grille Emblem Logo          |         | \$43.10  |
| 4   | 1   | Front Bumper Lower Center Garnish |         | \$123.50 |
| 5   | 1   | Front Air Cooler Tank             |         | \$374.50 |
| 6   | 1   | Front Air Cooler Tank Duct        |         | \$120.00 |
| 7   | 1   | Front Air Cooler Tank Hose        |         | \$284.50 |

Subtotal :- \$1,556.90

429.50

Supplementary: 322.12