



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No. 0				
			Document Date 24/03/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	26/10/2017	SLT3446E	0	60645	66TP/SLT3446E/120321
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU203575021		2ZRS107337	60	Shashitharan	17/03/2021 8.00		24/03/2021 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:GBK2617B ACC DATE:11/03/21 TOW IN:11/03/21 @1930 DATE-IN: DATE SURVEY:16/03/21 NO OF REPAIR DAYS:8 BY:rasul AUTHORISED ON:				50.00	
2	B	BP-LAB2 CHECK WIRIN AND CONDUCT LEAK TEST	*			180.00	
3	B	BP-LAB2 TRANSFER DOOR MECHANISM	*			360.00	
4	B	BP-LAB2 R/I INTERIOR UPHOLSTERY TO FAC REPAIR	*			720.00	
5	B	BP-MECH2 CONDUCT WHEEL ALIGNMNET		BP59		180.00	
6	B	BP-MECH2		BP59			
7	B	BP-MECH2 RESET ECU UPON COMPLETION OF REPAIR		BP59		180.00	
8	Z	BP-SLANT SUPPLY SEALANT (NETT)				80.00	
9	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA	*			3600.00	
10	B	BP-RES2 RESRPAY ACC AFF AREA	*			2360.00	
11	S	BP-SUBLET INSTALL TYRE TO NEW RIM AND CONDUCT BALANCING	0239			80.00	
12	1	T08826-08115 PANEL BONDING AD	1.00	267.20		267.20	
13	2	U61601-47150 PANEL SUB-ASSY,	1.00	871.50		871.50	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Company Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

**TOYOTA****ESTIMATE**

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No.				
			0				
			Document Date				
			24/03/2021				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	26/10/2017	SLT3446E	0	60645	66TP/SLT3446E/120321

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FU203575021	2ZRS107337	60	Shashitharan	17/03/2021 8.00	24/03/2021 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	3	U58745-47030 PROTECTOR, QUARTER	1.00	22.90		22.90
15	4	U67003-47211 PANEL SUB-ASSY, RR	1.00	1294.90		1294.90
16	5	U75979-47070 STRIPE, RR DOOR,	1.00	15.40		15.40
17	6	U75987-47060 STRIPE, RR DOOR,	1.00	34.90		34.90
18	7	U75977-47080 STRIPE, RR DOOR,	1.00	21.90		21.90
19	8	U75850-47910 MOULDING ASSY,	1.00	594.80		594.80
20	9	U42611-47450 WHEEL, DISC	1.00	1879.40		1879.40
21	0	YTDG19-565R1 5 GRAB DUNLOP TYRE	1.00	245.00		245.00

For & on behalf of		Customer's Signature	Charge Summary		Total	13,037.90
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts	5,247.90	GST 7.00%	912.65
			Labour	7,710.00	Less	0.00
			Sublet	80.00		
			Lubrication/Fluid	0.00		
			Others	0.00	Amount Due	13,950.55

Company Copy

Vehicle Diagnostic Report

300539 km

JTDKB3FU203575021

Borneo Motors

Printed By: Default User(1)

23/03/2021 11:43:22 AM

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed			
ABS/VSC/TRC	Yes	C1425			X		-	F152647416	No
Steering Angle Sensor								8924G0K010	
Main Body	No	B2323			X		-	8922F4702005	No
SRS Airbag	No	B1921			X		-	8917F47191	No
Hybrid Control							Icon	899834736300	No
								899854701400	
Engine							-	896634765100	No
								8966A4703000	
Motor Generator							-	898841002200	No
								898841001200	
Cruise Control							-	-	No
Parking Assist Camera							-	867B016170	No
								867B1F116A	
EMPS							-	8965B47023	No
Air Conditioner							-	8865F4703102	No
Combination Meter							-	838000075401	No
								838000075701	
								838000075501	
								838000076001	
D-Door Motor							-	-	No
Entry&Start							-	-	No
P-Door Motor							-	-	No
RR-Door Motor							-	-	No
RL-Door Motor							-	-	No
Master Switch							-	-	No
Rain and/or Humidity Sensor							-	-	No
Navigation System							-	-	No
Power Source Control							-	-	No
HL AutoLeveling							-	-	No
Central Gateway							-	8911F4701002	No
Head Up Display							-	831084708002	No

Vehicle Diagnostic Report

300539 km

JTDKB3FU203575021

Borneo Motors

Printed By: Default User(1)

23/03/2021 11:45:21 AM

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed			
Hybrid Control							Icon	899834736300	No
Engine								899854701400	
								896634765100	No
Motor Generator								8966A4703000	
								898841002200	No
								898841001200	
Cruise Control								-	No
Parking Assist Camera								867B016170	No
								867B1F116A	
ABS/VSC/TRC								F152647416	No
Steering Angle Sensor								8924G0K010	
EMPS								8965B47023	No
Air Conditioner								8865F4703102	No
Combination Meter								838000075401	No
								838000075701	
								838000075501	
								838000076001	
Main Body								8922F4702005	No
D-Door Motor								-	No
Entry&Start								-	No
P-Door Motor								-	No
RR-Door Motor								-	No
RL-Door Motor								-	No
Master Switch								-	No
SRS Airbag								8917F47191	No
Rain and/or Humidity Sensor								-	No
Navigation System								-	No
Power Source Control								-	No
HL AutoLeveling								-	No
Central Gateway								8911F4701002	No
Head Up Display								831084708002	No

Customer

Vehicle ident no.

Repair order no.
R001253Technician
M-59Date/Time
23.3.21 12:55License plate no.
SLT3446E

First reg. date

Model
TOYOTA PRIUS ZVW50ROdometer reading: km/miles
300539

Complaints or reason for alignment check

			Before	Target Data	Actual
Rear axle	Camber	left	-1°30'	-1°15' +/-0°45'	-1°34'
		right	-1°31'		-1°32'
		cross	0°01'	0°00' +/-0°45'	-0°02'
	Toe	left	0°04'	0°05' +/-0°05'	0°04'
		right	0°02'		0°01'
		total	0°06'	0°11' +/-0°11'	0°04'
	Geometrical driving axis		0°01'	0°00'	0°02'
Front axle	Camber	left	-0°01'	-0°10' +/-0°45'	0°04'
		right	-0°24'		-0°31'
		cross	0°23'	0°00' +/-0°45'	0°36'
	Caster	left	6°28'	6°10' +/-0°45'	6°28'
		right	6°26'		6°26'
		cross	0°02'	0°00' +/-0°45'	0°02'
	SAI	left	12°40'	13°20'	12°35'
		right	13°26'		13°33'
		cross	-0°46'	0°00'	-0°59'
	Track differential angle	left			
		right			
	Toe	left	-0°03'	0°03' +/-0°05'	0°00'
		right	-0°12'		0°02'
		total	-0°15'	0°05' +/-0°11'	0°02'
	Setback			0°00'	
	Max steering lock	left steer	left	-42°00' +/-2°00'	
			right	35°00' +/-2°00'	
		right steer	left	35°00' +/-2°00'	
			right	-42°00' +/-2°00'	