

(08/11/13) wef

ASS. REC. BY: Paul

REF:

CS/CTI 21003435/R19f3

2006

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLT 34466at Workshop m/s BORNEO MOTORof 2, PANDAN CRESCENTInsured: CTIPolicy No. DMUCVSNW00016382101Claims No. SNM 21D 201465002


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 74K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLT 34466 Yr Regn: 2011 / OCTType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS HYBRID 1.8 CVT c.c. 1798Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 300538 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 3TDKB3FU203595021Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 11/03/21D.O.I. 16/03/2021Survey held at BORNEO MOTORDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orO/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit - 37K

26/3/21 @ 2.40pm revised to Jenny Lee via merimen.

25/3/21 @ 9.16am Pams finalised with Shashi final fig @ 13037.90, 8 days.

Date/Time, File Pass to?

1) 26/3 11.00am ☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 8Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format: MER-TPLump Sum / I.B.I.: (\$ 13037.90)



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925
	Document No. 0	
	Document Date 15/03/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	26/10/2017	SLT3446E	0	60645	66TP/SLT3446E/120321

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FU203575021	2ZRS107337	60	Shashitharan	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:GBK2617B ACC DATE:11/03/21 TOW IN:11/03/21 @1930 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 100.00
2	B	BP-LAB2 CHECK WIRIN AND CONDUCT LEAK TEST				180.00
3	B	BP-LAB2 TRANSFER DOOR MECHANISM				360.00
4	B	BP-LAB2 R/I INTERIOR UPHOLSTERY TO FAC REPAIR				720.00
5	B	BP-MECH2 CONDUCT WHEEL ALIGNMENT				180.00
6	B	BP-MECH2 REPL RH UNDERCARRIAGE				720.00
7	B	BP-MECH2 RESET ECU UPON COMPLETION OF REPAIR				180.00
8	Z	BP-SLANT SUPPLY SEALANT (NETT)				80.00
9	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA @120				3600 4320.00
10	B	BP-RES2 RESRPAY ACC AFF AREA @590				2360 3540.00
11	L	BP-LPO SUPPLY TYRE 1 PC (PO#) cut				245 350.00
12	S	BP-SUBLET INSTALL TYRE TO NEW RIM AND CONDUCT BALANCING				80.00
13	1	T08826-08115 PANEL BONDING AD	1.00	267.20		267.20

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
THIRD PARTY CLAIM				S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925			
				Document No. 0					
				Document Date 15/03/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	ZVW50R	AHXEBW Q2	26/10/2017	SLT3446E	0	60645	66TP/SLT3446E/120321		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDKB3FU203575021		2ZRS107337	60	Shashitharan	--/--/----		0.00	--/--/----	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
14	2	T52159-47913 COVER, RR BUMPER <i>repair</i>				1.00	442.60		442.60
15	3	T52565-47900 FILLER, RR BUMPER <i>repair</i>				1.00	123.70		123.70
16	4	T61601-47150 PANEL SUB-ASSY, <i>bt repair</i>				1.00	871.50		871.50
17	5	T58745-47030 PROTECTOR, QUARTER <i>new</i>				1.00	22.90		22.90
18	6	T67895-47011 WEATHERSTRIP, RR <i>? xsvc</i>				1.00	36.20		36.20
19	7	T67003-47211 PANEL SUB-ASSY, RR <i>bt</i>				1.00	1294.90		1294.90
20	8	T67871-47051 WEATHERSTRIP, RR <i>? xsvc</i>				1.00	180.10		180.10
21	9	T75979-47070 STRIPE, RR DOOR, <i>new</i>				1.00	15.40		15.40
22	0	T75987-47060 STRIPE, RR DOOR, <i>new</i>				1.00	34.90		34.90
23	1	T75977-47080 STRIPE, RR DOOR, <i>new</i>				1.00	21.90		21.90
24	2	T62505-47011 COVER SUB-ASSY, <i>? xsvc</i>				1.00	207.30		207.30
25	3	T75850-47910 MOULDING ASSY, <i>new form</i>				1.00	594.80		594.80
26	4	T48530-80791 ABSORBER SET, SHOCK, <i>? xsvc</i>				1.00	127.00		127.00
27	5	T48770-47010 ARM ASSY, UPR <i>? xsvc</i>				1.00	420.80		420.80
28	6	T48730-47010 ARM ASSY, RR <i>? xsvc</i>				1.00	497.50		497.50
29	7	T48760-47010 ARM ASSY, TRAILING, <i>? xsvc</i>				1.00	370.40		370.40
30	8	T48717-47020 BRACKET, RR <i>? xsvc</i>				1.00	107.20		107.20
31	9	T48717-47020 BRACKET, RR <i>? xsvc</i>				1.00	107.20		107.20
32	0	T48710-47010 ARM ASSY, RR <i>? xsvc</i>				1.00	239.20		239.20
33	1	T42304-47050 CARRIER SUB-ASSY, RR <i>? xsvc</i>				1.00	953.60		953.60
For & on behalf of Borneo Motors (Singapore) Pte Ltd				Customer's Signature		Charge Summary		Total	
				Please acknowledge receipt of vehicle		Parts		Less	
						Labour			
						Sublet			
						Lubrication/Fluid			
						Others			
								Amount Due	

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd			
			Document No. 0		6 Battery Road #38-04 Singapore 049909			
			Document Date 15/03/2021		Work: 65703925			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q2	26/10/2017	SLT3446E	0	60645	66TP/SLT3446E/120321	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU203575021		2ZRS107337	60	Shashitharan	--/--/----		0.00 --/--/----	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
34	2	T42450-76020 HUB & BRG ASSY, RR ? x svc			1.00	610.20		610.20
35	3	T42611-47450 WHEEL, DISC cut ✓			1.00	1879.40		✓1879.40
36	4	T42602-47181 CAP SUB-ASSY, WHEEL ? x svc			1.00	211.50		211.50
37	5	T81581-47011 LENS & BODY, RR ? x svc			1.00	502.00		502.00
<i>Rasul</i> <i>Hp 90010068</i> <i>8 days</i> <i>16/03/2021 @ 1655</i> <i>Resurvey before paint</i>					LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total 20,949.40		
		Please acknowledge receipt of vehicle		Parts 10,139.40 Labour 10,380.00 Sublet 430.00 Lubrication/Fluid 0.00 Others 0.00		GST 7.00% 1,466.46 Less 0.00 Amount Due 22,415.86		

Customer Copy