



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
NTUC INCOME INSURANCE CO-OPERATIVE LTD 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 ATTN: ABDUL RASHID			Ref: CS3/INC19021406/R1qf3e2-1 Date: 25/03/2021 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLL 4738Z	Veh. Inspected	FQ 4656X	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1067684-002	Excess (\$)	0.00	
Assign From	ABDUL RASHID	Assign Date	16/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STEED VLS	c.c	398	
Engine No.	HIDDEN	Year of Reg.	1998	
Chassis No.	NC371001827	Colour	BLACK	
Odometer	75100 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	90/90-21	METZELER	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	170/80 R18	METZELER	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/10/2019	Inspection Date	03/12/2019	
Survey held at	160 SIN MING DRIVE #05-20 SINGAPORE 575722			
Repairer	LIM SIANG CHOW AUTO SERVICE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	