

Repair Estimate


Automobile Hub Enterprise

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883
Tel: (65) 9786 4483 Fax: (65) 6509 6584 Email: autohub325@gmail.com

Make/Model: TOYOTA

SLE8559J

ANH208286562



TPAXA
Veron.

List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper <i>Behor-d</i>	1	\$ 1,769.00	\$ 1,769.00
2	Rear bumper reflector <i>n/s o/s. New</i>	1	\$ 161.00	\$ 161.00
3	Rear bumper reverse sensor wire <i>new</i>	1	\$ 280.00	\$ 280.00
4	Rear bumper side bracket <i>new</i>	2	\$ 89.00	\$ 178.00
5	Rear bumper side retainer <i>RH new</i>	2	\$ 89.00	\$ 178.00
6	Rear bumper top corner garnish <i>n/s o/s. new</i>	1	\$ 624.00	\$ 624.00
7	Rear bumper towing cover <i>n/s o/s. new</i>	1	\$ 67.00	\$ 67.00
8	Rear bumper under shield <i>n/s o/s. new</i>	1	\$ 269.00	\$ 269.00
9	Rear end panel inner <i>new</i>	1	\$ 513.00	\$ 513.00
10	Rear end panel outer <i>new</i>	1	\$ 513.00	\$ 513.00
11	Rear end panel top garnish <i>new</i>	1	\$ 339.00	\$ 339.00
12	Rear fender inner trimboard <i>n/s o/s. new</i>	1	\$ 856.00	\$ 856.00
13	Rear spare wheel panel <i>new</i>	1	\$ 988.00	\$ 988.00
14	Rear fender cowlings <i>n/s o/s. new</i>	1	\$ 338.00	\$ 338.00
			Subtotal	\$ 7,073.00
			List discount	
			Total	\$ 7,073.00

1136

89

1225

918.75

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper clips <i>new</i>	10	\$ 5.50	\$ 55.00
2	Rear bumper top corner garnish n/s clips <i>new</i>	6	\$ 5.50	\$ 33.00
3	Rear bumper under shield n/s clips <i>new</i>	8	\$ 5.50	\$ 44.00
4	Rear end panel inner sealant <i>new</i>	1	\$ 100.00	\$ 100.00

50

10

Repair Estimate

5	Rear end panel outer sealant	1	\$ 100.00	\$ 100.00	+
6	Rear end panel top garnish clips	6	\$ 5.50	\$ 33.00	+
7	Rear spare wheel panel sealant	1	\$ 100.00	\$ 100.00	+
8	Rear fender cowling n/s clips	8	\$ 5.50	\$ 44.00	+
9	Rear buzzer sensor	1	\$ 320.00	\$ 320.00	+
10	Rear buzzer sensor centre cover n/s	1	\$ 39.00	\$ 39.00	+
11	Rear buzzer sensor centre n/s	1	\$ 482.00	\$ 482.00	+
12	Rear buzzer sensor corner cover n/s	1	\$ 39.00	\$ 39.00	+
13	Rear reverse sensor corner n/s	1	\$ 482.00	\$ 482.00	200
14	Sundries	1	\$ 50.00	\$ 50.00	+
			Total	\$ 1,921.00	240

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To measure, drill holes on replaced rear bumper, position and install reverse sensor, check, test distance and functions.	0.25	\$ 50.00
4	Supply spray paint material and necessary items to respray rear bumper, n/s rear top corner garnish, end panel and other affected area / panel.	6	\$ 1,200.00
5	To rust proof all affected portions after repair.	0.5	\$ 100.00
		Total labour	\$ 2,600.00

Estimate Grand Total	\$ 11,594.00
-----------------------------	---------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 1638.75
L/S: 1.31K
02 Days