


Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Guan Motor
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 12 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SK E 11552 Yr Regn: 02 12
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai Elante c.c. 1591
 Colour: M.Silver A/C: Insured / Std / NI / NA
 Sp.Reading: 220025 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMH0H41CMCU423160
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brakes: Inorder / Jammed / Leaked / Burnt or _____
 Modl: NI / S/Rim / STD A/Rim or _____
 Tyre Size: F: 205/55R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake
 Front: _____ Rear: _____
 R/Bal. 8 mm R/Bal. 8 mm
 L/Bal. 8 mm L/Bal. 8 mm
 D.O.A. 12/3/21 D.O.I. 17/3/2021
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rec N/S & R/O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Got BZ</u>

Date/Time, File Pass to?

☐ : Prell. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech Invs (\$ _____)
☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SKE1155Z

No.	Qty	List Items			
1	1	Front bumper	Bu/lem	474.60	✓
2	1	Front bumper tow cover	\$ nu	26.00	✓
3	1	Front bumper RH fog lamp	\$ fu	115.40	X
4	1	Front bumper RH side retainer	\$ di	32.00	✓
5	1	Front bumper inner foam	\$	110.70	?
6	1	Front bumper inner reinforcement	\$	695.80	?
7	1 set	Rear bumper clips	\$ nu	30.00	✓
8	1	RH headlamp	\$	1,198.80	?
9	1	Front RH fender	\$ R	966.80	X
10	1	Rear bumper	\$ R	459.40	✓
11	1	Rear bumper LH reflector	\$ CM	32.00	✓
12	2	Rear bumper side retainer	nls \$ CM	88.60	✓
13	1 set	Rear bumper clips	\$ nu	30.00	✓
14	2	Rear bumper inner bracket (Top & bottom)	\$ CM	180.00	✓
15	1	Rear bumper inner reinforcement	\$ CM	294.80	✓
16	1	Rear bumper inner reinforcement LH bracket	\$ R	75.30	✓
17	1	LH taillamp	\$ R	876.80	✓
18	1	LH taillamp panel	\$ R	162.00	✓
19	1	Rear boot lid	\$ R	1,528.10	✓
20	1	Rear boot LH side reflector/lamp	\$ CM	664.20	✓
21	1	Rear boot centre "H" logo	\$ nu	34.00	✓
22	1	Rear boot LH "HYUNDAI" emblem	\$ nu	56.00	✓
23	1	Rear boot RH "ELANTRA" emblem	\$ nu	48.80	✓
24	2	Rear boot hinge	nls \$ R	178.00	✓
25	1	Rear boot inner trim	\$ Refum	306.00	✓
26	1 set	Rear boot inner trim clips	\$ nu	60.00	✓
27	1	Rear boot top lock	\$ nu	116.20	✓
28	1	Rear boot lower lock catch	\$ R	24.10	X
29	1	Rear boot weatherstrip	di \$ nu	96.40	50% in
30	1	Rear end panel	\$ R	382.40	✓
31	1	Rear end panel top garnish	\$ di	65.40	✓
32	1	Rear spare tyre panel	\$	647.00	?
33	1	Rear spare tyre top board	\$	219.40	?
34	1	Rear LH fender	\$ nu	1,096.00	✓
35	1	Rear LH fender under splash shield	\$ fu	64.00	X
36	1 set	Rear fender under splash shield clips	\$ nu	30.00	X
37	1	Rear LH fender 1/4 glass moulding	\$ nu	53.00	✓
38	1	Rear LH fender inner side trim	\$ Refum	348.00	✓
39	1 set	Rear fender inner side trim clips	\$ nu	60.00	✓
			\$	11,926.00	
Less 20%			\$	2,385.20	
Total :			\$	9,540.80	

NOT Authorised
Lily @

12 days

Mercury After Pain

Special Nett Items

40	1	Front number plate	\$	45.00	X
41	1 set	Reverse sensors	\$	250.00	2000
42	1	Rear number plate	\$	45.00	X
43	1 set	Rear windscreen sealant	\$	50.00	4000
44	1 set	Rear end panel sealant	\$	50.00	3000
Total :			\$	440.00	

Labour

1	Labour Charges for remove/refit, panel beat and replacement of damages.	\$	1,600.00	1400
2	To putty and spray Spray Paintings charges.	\$	1,400.00	1200
3	To check wirings and lightings for front & rear porion.	\$	80.00	400
4	To remove. Refit rear windscreen glass.	\$	140.00	1200
5	To remove, refit rear LH fender 1/4 glass.	\$	100.00	500
6	To transfer rear boot lid fittings.	\$	80.00	600
7	To remove, refit reverse sensors.	\$	70.00	500
8	To remove, refit roof lining, rear cushion and attachments.	\$	200.00	1200
9	To supply and apply anti rust treatment	\$	120.00	900
Total :			\$	3,790.00

Total Parts and Labour : \$ 13,770.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "No Win - No Fee" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SINGAPORE POLICE FORCE



T/20210312/7039

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 4

Report No. T/20210312/7039

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/03/2021 22:43		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: LEE KOK SENG			Address: 684A WOODLANDS DRIVE 73 #10-215 SINGAPORE 731684		
ID Type / ID No.: NRIC NO / S7146782A			Contact No.: Home/Office: Mobile: 90478017		
Nationality: SINGAPORE CITIZEN			Email: lee2630@singnet.com.sg		
Sex: Male	Age: 49	Date of Birth: 30/12/1971	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Financial/Investment adviser			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 12/03/2021 17:05	Type of Location: Straight Road
Location: THOMSON ROAD				
Weather: Clear	Road Surface: Dry		Road Speed Limit: 50 Km/h	
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of
SHB4948J	Car	HYUNDAI	i40	Yellow	Slightly Damaged	0
SJJ21T	Car	AUDI	A8	Black	Slightly Damaged	0



SINGAPORE POLICE FORCE



T/20210312/7039

2 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20210312/7039

CONTINUATION OF REPORT


Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of
SKE1155Z	Car	HYUNDAI	ELANTRA 1.6 AT ABS D/AB 2WD 4DR	Silver	Seriously Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKE1155Z	NTUC Income Insurance Co-Operative Limited	5116595722	12/03/2020	08/08/2021

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	ONG POH LYE		ID No.	S1100980H
Related Vehicle	SHB4948J (Car)		Contact No.	93803221
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave		NIL	Degree of	NIL
Driver				
Name	HADI WIDJAJA TANAGA		ID No.	S2589008F
Related Vehicle	SJJ21T (Car)		Contact No.	96330021
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave		NIL	Degree of	NIL



**SINGAPORE
POLICE FORCE**



T/20210312/7039

3 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20210312/7039

CONTINUATION OF REPORT

Driver			
Name	LEE KOK SENG	ID No.	S7146782A
Related Vehicle	SKE1155Z (Car)	Contact No.	90478017
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date	12/03/2021	Date	12/03/2021
No. of Days granted Medical Leave	05	Degree of	Slight

Brief Details.

On 12 Mar 2021 about 5.05pm, while driving on the 3rd lane along Thomson Road (besides Velocity@Novena Square) near the Mouline Road, my vehicle (Car B - SKE1155Z) has stopped behind vehicle Car A (SHB4948J) due to slow traffic followed by Red Light. Suddenly, vehicle Car C (SJJ21T) knocked hard onto my car rear. Due to great knocking impact, my car surged forward and knocked slightly onto Car B.

Due to that knocking impact, I hit my chest onto the steering wheel with my seat belt fastened and hit my head onto the seat's head rest. This resulted me feeling slightly giddy, neck pain and chest pain. After the car being towed to workshop at Autocare at Sin Ming Drive, I have proceeded to A&E at Mount Alvenia Hospital to seek medical consultation and have given 5 days medical leave till 16 Mar 2021 and being advised to consult doctor if the pain still persist on next Monday (15 Mar 2021).

For this accident, I have taken photos of the vehicles involved, the particulars of all drivers and have extracted the video footage from my car front camera.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 15/03/2021 10:14 (SGT)
Date of Accident 12/03/2021 17:05 (SGT)
Exact Location of Accident Near 218 Moulmein Rd, Singapore 308105
Additional Location Information ALONG THOMSON ROAD TOWARDS MOULEIN ROAD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKE1155Z

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner LEE KOK SENG
NRIC No SXXXX782A
Email Address lee2630@signet.com.sg
Mobile Phone No (Phone) +65-90478017
Alternative Phone No +65-90478017

VEHICLE PARTICULARS

Manufacturer Hyundai
Model Elantra
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private hire


INSURANCE COMPANY

Name of Insurance Company NTUC
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5116595722
Cover Note Number -

DRIVER

Name of Driver LEE KOK SENG
NRIC No SXXXX782A
Date Of Birth 30/12/1971
Occupation Outdoor

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the Police Report.

Please note the vehicles involved are as follows:

Car B → SKE1155Z

Car C → SJJ21T

Car A → SHB4948J

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 12/3/2021

Driver's Signature

(If driver is not the policyholder)

Date & Time: 12/3/2021

Reporting Centre Person's Signature

Name:

NRIC/PIN No.:

