



源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SKE11552

No.	Qty	List Items		
1	1	Front bumper	Buy/cm	474.60 ✓
2	1	Front bumper tow cover	\$ nu	26.00 ✓
3	1	Front bumper RH fog lamp	\$ cm	115.40 X
4	1	Front bumper RH side retainer	\$ nu	32.00 ✓
5	1	Front bumper inner foam	\$ cm	110.70 ✓
6	1	Front bumper inner reinforcement	\$ nu	695.80 ✓
7	1 set	Rear bumper clips	\$ nu	30.00 ✓
8	1	RH headlamp	my \$ cm	1,198.80 ✓
9	1	Front RH fender	\$ nu	966.80 X
10	1	Rear bumper	\$ nu	459.40 ✓
11	1	Rear bumper LH reflector	\$ cm	32.00 ✓
12	2	Rear bumper side retainer	nls \$ cm	88.60 ✓
13	1 set	Rear bumper clips	\$ nu	30.00 ✓
14	2	Rear bumper inner bracket (Top & bottom)	\$ cm	180.00 ✓
15	1	Rear bumper inner reinforcement	\$ cm	294.80 ✓
16	1	Rear bumper inner reinforcement LH bracket	\$ nu	75.30 ✓
17	1	LH taillamp	\$ nu	876.80 ✓
18	1	LH taillamp panel	\$ nu	162.00 ✓
19	1	Rear boot lid	\$ nu	1,528.10 ✓
20	1	Rear boot LH side reflector/lamp	\$ cm	664.20 ✓
21	1	Rear boot centre "H" logo	\$ nu	34.00 ✓
22	1	Rear boot LH "HYUNDAI" emblem	\$ nu	56.00 ✓
23	1	Rear boot RH "ELANTRA" emblem	\$ nu	48.80 ✓
24	2	Rear boot hinge	nls \$ nu	178.00 ✓
25	1	Rear boot inner trim	\$ return	306.00 ✓
26	1 set	Rear boot inner trim clips	\$ nu	60.00 ✓
27	1	Rear boot top lock	\$ nu	116.20 ✓
28	1	Rear boot lower lock catch	\$ nu	24.10 X
29	1	Rear boot weatherstrip	nls \$ nu	96.40 ✓
30	1	Rear end panel	\$ nu	382.40 ✓
31	1	Rear end panel top garnish	\$ nu	65.40 ✓
32	1	Rear spare tyre panel	\$ nu	647.00 X
33	1	Rear spare tyre top board	\$ nu	219.40 X
34	1	Rear LH fender	\$ nu	1,096.00 ✓
35	1	Rear LH fender under splash shield	\$ nu	64.00 X
36	1 set	Rear fender under splash shield clips	\$ nu	30.00 X
37	1	Rear LH fender 1/4 glass moulding	\$ nu	53.00 ✓
38	1	Rear LH fender inner side trim	\$ return	348.00 ✓
39	1 set	Rear fender inner side trim clips	\$ nu	60.00 ✓
			\$	11,926.00
Less 20%			\$	2,385.20
Total :			\$	9,540.80

NOT Notified

L1 Sy @ 5800.

Penny After Pain

12 days

Special Nett Items

1 Front number plate	\$ 45.00	X
1 set Reverse sensors	\$ 250.00	20W
1 Rear number plate	\$ 45.00	X
1 set Rear windscreen sealant	\$ 50.00	40W
1 set Rear end panel sealant	\$ 50.00	30W
Total :	\$ 440.00	

Labour

Labour Charges for remove/refit, panel beat and replacement of damages.	\$ 1,600.00	1400L
To putty and spray Spray Paintings charges.	\$ 1,400.00	1200L
To check wirings and lightings for front & rear porion.	\$ 80.00	40L
To remove. Refit rear windscreen glass.	\$ 140.00	120L
To remove, refit rear LH fender 1/4 glass.	\$ 100.00	50L
To transfer rear boot lid fittings.	\$ 80.00	60L
To remove, refit reverse sensors.	\$ 70.00	50L
To remove, refit roof lining, rear cushion and attachments.	\$ 200.00	120L
To supply and apply anti rust treatment	\$ 120.00	90L
Total :	\$ 3,790.00	

Total Parts and Labour : \$ 13,770.80

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date: