



JEC AUTO SERVICE PTE LTD UEN: 202034846C
 1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883
 Tel : (65) 6509 6585 Fax : (65) 6509 6584 Mobile : (65) 9232 7457
 Email : jecautoservice@yahoo.com.sg

To : China Taiping
Vehicle : GBK 5191 S
Make : Toyota Dyna
Date : DOA 13 March 2021

Date : 15-Mar-2021
Page No : 1

Quotation 21/03/21

S/n	Description	Unit	Unit Price (S\$)	Prices (S\$)
1	Front Top Panel		289.31	
2	Front Center Panel		1031.63	
3	Front Grille		528.24	
4	Front Logo		68.93	
5	Front Headlamp LH		925.12	
6	Front Headlamp RH		925.12	
7	Front Grille Lower			
8	Front Bumper		692.59	
9	Front Bumper Bracket		265.42	
10	Front Bumper Reinforcement		216.88	
11	Front Number Plate		80.00	
12	Front Side Panel - LH		235.08	
13	Front Side Panel - RH		235.08	
14	Front Wiper Motor		990.41	
15	Front Wiper Arm		124.49	
16	Front Windscreen		1288.29	
17	Dashboard Assembly		1029.93	
18	Air-Con Blower Assembly		1871.74	
19	Air-Condenser		1482.01	
20	Air-Con Pipe (inlet)			
21	Air Con Pipe (outlet)			
22	Brake Booster Assembly		1181.43	
23	Brake Fluid Cylinder		261.89	
24	Brake Pedal Assembly		319.91	
25	Steering Column		1243.84	
26	Power Steering Fluid Reservoir		297.04	
27	Clutch Booster Assembly			
28	Clutch Pedal Assembly		276.75	
	Nett Item			
1	Front Top Panel Clips		7.60	
2	Front Center Panel Clips		7.60	
3	Front Grille Clips		8.75	

 JEC AUTO SERVICE PTE LTD UEN: 202034846C 1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883 Tel : (65) 6509 6585 Fax : (65) 6509 6584 Mobile : (65) 9232 7457 Email : jecautoservice@yahoo.com.sg				
4	Front Grille Lower Clips		7.60	
5	Front Logo (Toyota)		67.16	
6	Sealant		60.00	
7	Windscreen Moulding		297.75	
	Labour			
1	Panel Beating, Refix, Reinstalling, Replacement		2,000.00	
2	Refocusing of Headlamp		160.00	
3	Spraying of the affected parts		1,200.00	
4	Remove and Refix Windsceen		200.00	
5	Water Testing		120.00	