



JEC AUTO SERVICE PTE LTD

UEN: 202034846C

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883
Tel : (65) 6509 6585 Fax : (65) 6509 6584 Mobile : (65) 9232 7457
Email : jecautoservice@yahoo.com.sg

To : China Taiping

Vehicle : GBK 5191 S

Make : Toyota Dyna

Date c : DOA 13 March 2021

Date : 15-Mar-2021

Page No : 1

Quotation 21/03/21

JTFAT3SY101C215345

OD China Veron.

S/n	Description	Unit	Unit Price (S\$)	Prices (S\$)
1	Front Top Panel <i>Deated</i>		289.31	✓
2	Front Center Panel <i>Deated</i>		1031.63	✓
3	Front Grille <i>Caused</i>		528.24	✓
4	Front Logo <i>Re</i>		68.93	✓
5	Front Headlamp LH <i>nt</i>		925.12	✓
6	Front Headlamp RH <i>embled</i>		925.12	✓
7	Front Grille Lower <i>Neu</i>			x
8	Front Bumper <i>Regr</i>		692.59	x
9	Front Bumper Bracket <i>3rd</i>		265.42	+
10	Front Bumper Reinforcement <i>3rd</i>		216.88	x.
11	Front Number Plate <i>Neu</i>		80.00	x.
12	Front Side Panel - LH <i>Regr</i>		235.08	x
13	Front Side Panel - RH <i>Neu</i>		235.08	+
14	Front Wiper Motor <i>3rd</i>		990.41	+
15	Front Wiper Arm <i>3rd</i>		124.49	+
16	Front Windscreen <i>Re</i>		1288.29	+
17	Dashboard Assembly <i>Neu</i>		1029.93	+
18	Air-Con Blower Assembly <i>embled</i>		1871.74	✓
19	Air-Condenser <i>Re</i>		1482.01	+
20	Air-Con Pipe (inlet) <i>2. NTP</i>			+
21	Air Con Pipe (outlet) <i>Neu</i>			+
22	Brake Booster Assembly <i>3rd</i>		1181.43	x
23	Brake Fluid Cylinder <i>3rd</i>		261.89	x.
24	Brake Pedal Assembly <i>Neu</i>		319.91	x.
25	Steering Column <i>Neu</i>		1243.84	x
26	Power Steering Fluid Reservoir <i>Neu</i>		297.04	x
27	Clutch Booster Assembly <i>3rd</i>			+
28	Clutch Pedal Assembly <i>3rd</i>		276.75	x
29	Wiper Washer Tank (A) Deformed		115	✓
	Nett Item			
1	Front Top Panel Clips <i>Neu</i>		7.60	x
2	Front Center Panel Clips <i>Neu</i>		7.60	p
3	Front Grille Clips <i>Neu</i>		8.75	✓



JEC AUTO SERVICE PTE LTD UEN: 202034846C
 1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883
 Tel : (65) 6509 6585 Fax : (65) 6509 6584 Mobile : (65) 9232 7457
 Email : jecautoservice@yahoo.com.sg

4	Front Grille Lower Clips <i>new</i>		7.60	<i>+</i>
5	Front Logo (Toyota) <i>new</i>		67.16	<i>✓</i>
6	Sealant <i>new</i>	<i>433.66</i>	60.00	<i>—</i>
7	Windscreen Moulding <i>new</i>		297.75	<i>✓</i>
	Labour			
1	Panel Beating, Refix, Reinstalling, Replacement		2,000.00	<i>800</i>
2	Refocusing of Headlamp		160.00	<i>30</i>
3	Spraying of the affected parts	<i>1750</i>	1,200.00	<i>800</i>
4	Remove and Refix Windscreen		200.00	<i>120</i>
5	Water Testing		120.00	<i>+</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian Lj
Not Authorized.
P/P 17/03/21.
Excess \$350.

total: 6499.97
CP/P
06 Days.