

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

ALG-CLB) JU

Date: 16.03.2021
Time: 14:32:44
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305458923
REGN NO : SH 8229M
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 21.07.2016
DATE/TIME IN : 16.03.2021 11:35
ACCIDENT DATE : 16.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	BUMPER W LIP & FOG LAMP C	1	1,052.20	20.00	841.76	de	
0002 04-01-0103-0782-A	LAMP ASSY-HEAD RH#	1	1,800.00	20.00	1,440.00	unt	
0003 04-01-0103-0573-A	PANEL-FENDER RH+	1	663.00	20.00	530.40	hb	3560-
0004 04-01-0103-0640-G	BRACKET-FR BUMPER SIDE RH	1	44.80	20.00	35.84	net	2848
						SUB-TOTAL :	2,848.00

JOB NATURE

0000 PB	PANEL BEATING	600.00	420
0001 SP	SPRAYPAINT CHARGE	600.00	500
0002 17-01	CHECK ALL LIGHTING	50.00	30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30
0004 20-05	RENEW ADVERTISEMENT STICKER-fender	100.00	unt 1080
		SUB-TOTAL :	1,400.00

Tanpin 9741 5745

WP' 16/3/21 @ 4pm

1/3 Resum after repair

2-3 days
Tanpin (Khandi-wm)

3928

1/583/50

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: