

Our Job Ref No : 305458790

Date : 25.03.21

COMFORTDELGRO

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr GUO QIANG

Vehicle Reg No. : SHA2499G CTPL

13.03.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **TOKIO MARINE** --- **GBC9554U**

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

20%

\$1,550.00

Final Lumpsum Repair cost

\$1,550.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 

Signature : _____

Name : LIM KWOK ENG

Name : _____

Tel : 62148316

Date : _____

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305458790
 REGN NO : SHA2499G
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 17.03.2016
 DATE/TIME IN : 15.03.2021 09:2
 ACCIDENT DATE : 13.03.2021

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0005 17-01 CHECK ALL LIGHTING	50.00				1,134.80
0020-22 REMOVE/REFIX REVERSE SENSOR	80.00				831
SUB-TOTAL : 1,030.00					1,965.80
TOTAL : 2,845.17					-20%
					1,572.64

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

2 Days
 Lino Qip
 15/3/21 @ 1630
 L/S \$1,550/-
 After repair photos.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Lee

Tofio Marini

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 15.03.2021

Time: 15:43:44

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305458790
REGN NO : SHA2499G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 17.03.2016
DATE/TIME IN : 15.03.2021 09:20
ACCIDENT DATE : 13.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1 L	1,106.00	20.00	884.80	/ TN
0002 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/ NEC
0003 04-01-0103-0738-G	COVER-RR BUMPER LWR#	1 L	228.00	20.00	182.40	/ GA.
0004 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	135.70	10.00	122.13	X NN
0005 04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	1.00-	50.00	/ NEC
0006 04-01-0103-0585-A	LAMP ASSY-RR COMB O/S RH#	1 L	697.80	20.00	558.24	?
SUB-TOTAL : 1,815.17						+ Net 50

JOB NATURE

0000 20-05	REAR BUMPER ADVERTISEMENT LOGO		50.00	/ bc
0001 20-05	REAR FENDER ADVERTISEMENT LOGO RH		100.00	/ { bc.
0002 20-05	REAR FENDER ADVERTISEMENT LOGO LH		100.00	
0003 L	PANEL BEATING	350.00	280	+ 250
0004 23-502	SPRAYPAINT ON AFFECTED AREA	300.00	250	+ 581
Merimen Charge #11				831
				1,965.80
				-20%
				1,572.64