

The Motor Claims Department  
M/s Lonpac Insurance Bhd  
100 Beach Road  
#19-00 Shaw Tower  
Singapore 189702

File No : - SH/2021/056/05/009/OD  
Date : 15-March-2021

*Not Authorized*  
*U/Sing &*  
*Resurvey After Paint*  
*Ex 81000k*

Estimated cost of repair for vehicle no : GBH5885P Citroen Berlingo  
Policy no: Z/20/VC00/107584 Accident Date: 12.03.2021

Description	Quantity	Cost Price
RH rear door	1	\$ 880.00 ✓
RH rear door emblem	1	\$ 80.00 ✓
RH rear door badge "Citroen"	1	\$ 75.00 ✓
RH rear door hinge top	1	\$ 140.00 X
RH rear door hinge bottom	1	\$ 140.00 X
RH rear door check	1	\$ 80.00 X
LH rear door	1	\$ 980.00 ✓
LH rear door badge "Berlingo"	1	\$ 75.00 ✓
LH rear door rear bumper plate lamp RH	1	\$ 70.00 ✓
LH rear door rear bumper plate lamp LH	1	\$ 70.00 X
LH rear door outer handle	1	\$ 95.00 X
LH rear door hinge top	1	\$ 140.00 ?
LH rear door hinge bottom	1	\$ 140.00 ?
LH rear door check	1	\$ 80.00 X
LH rear door wiper motor	1	\$ 380.00 ?
LH rear door wiper motor cover	1	\$ 70.00 ✓
LH rear door inner lock	1	\$ 240.00 ?
LH rear door third brake light	1	\$ 130.00 X
RH tail lamp	1	\$ 130.00 ✓
LH tail lamp	1	\$ 130.00 ✓
Centre rear bumper	1	\$ 260.00 ✓
RH rear bumper	1	\$ 150.00 X
LH rear bumper	1	\$ 150.00 ✓
RH Rear bumper parking sensors outer	1	\$ 150.00 ✓
LH Rear bumper parking sensors outer	1	\$ 150.00 ✓
RH Rear bumper parking sensors inner	1	\$ 150.00 ✓
LH Rear bumper parking sensors inner	1	\$ 150.00 ✓
RH Rear bumper parking sensors outer holder	1	\$ 35.00 ?
LH Rear bumper parking sensors outer holder	1	\$ 35.00 ?
RH Rear bumper parking sensors inner holder	1	\$ 35.00 ?
LH Rear bumper parking sensors inner holder	1	\$ 35.00 ?
Rear bumper tow cover	1	\$ 45.00 ✓
Rear bumper reinforcement	1	\$ 280.00 ✓
Rear end panel	1	\$ 240.00 ?
LH rear corner inner panel	1	\$ 250.00 ✓

RH rear wheel rim	1	\$	<i>Net</i> 180.00	✓
RH rear wheel rim hub cap	1	\$	<i>Net</i> 90.00	✓
LH rear wheel rim	1	\$	<i>Net</i> 180.00	✓
LH rear wheel rim cap	1	\$	<i>Net</i> 90.00	✓
Spare tyre wheel rim	1	\$	<i>Rt</i> 180.00	✓
Spare tyre wheel rim holder frame	1	\$	140.00	?
Fuel tank	1	\$	1,100.00	?
Fuel tank heat shield	1	\$	<i>Rt</i> 180.00	✓
LH Fuel tank fuel line protector cover	1	\$	190.00	?
Rear axle	1	\$	<i>Net</i> 1,300.00	✓
RH rear shock absorber	1	\$	110.00	?
<u>LH rear shock absorber</u>	1	\$	110.00	?
RH rear wheel bearing	1	\$	<i>Net</i> 90.00	✓
LH rear wheel bearing	1	\$	<i>Net</i> 90.00	✓
Engine bottom dust cover	1	\$	280.00	?
Engine bottom dust cover clips (1 set)	1	\$	25.00	?
Front windscreen	1	<i>N-C</i> \$	<i>(C/M)</i> 550.00	X ✓
		\$	11,125.00	
	Add 15%	\$	1,668.75	
		\$	12,793.75	

Spare tyre	1	S. nett	\$	<i>Per</i> 95.00	<i>Folia</i>
RH rear door glass sealant	1		\$	<i>Net</i> 60.00	<i>4000</i>
RH rear door glass inner rubber seal	1		\$	<i>Net</i> 28.00	✓
LH rear door glass sealant	1		\$	<i>Net</i> 60.00	<i>4000</i>
LH rear door glass inner rubber seal	1		\$	<i>Net</i> 28.00	✓
Front windscreen glass sealant	1		\$	<i>Net</i> 80.00	X 40 ✓
Front windscreen glass inner rubber seal	1		\$	<i>Net</i> 28.00	X ✓
Front windscreen IU bracket	1		\$	<i>Net</i> 25.00	X ✓
"C & C" badge	1		\$	<i>Net</i> 60.00	✓
"6 PAX" sticker	1		\$	<i>Net</i> 5.00	✓
"70 KMH" sticker	1		\$	<i>Net</i> 5.00	✓

To remove and reinstall RH rear door glass and conduct water leak test.	\$	80.00	<i>600</i>
To remove and reinstall LH rear door glass and conduct water leak test.	\$	80.00	<i>600</i>
To remove and reinstall front windscreen and conduct water leak test.	\$	<i>Net</i> 120.00	X ✓
To remove RH & LH rear suspension system and replace damaged parts	\$	240.00	<i>2200</i>
To perform computerised wheel alignment	\$	65.00	✓



To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, LH rear fender to straighten out rear chassis member and adjust rear body and rear doors alignment

\$ 840.00 700

To spray paint affected rear and inner damaged portion inclusive of preparatory works and material

\$ 850.00 750

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality

\$ 25.00 20

To perform computer diagnostic on rear parking system, drivetrain, ABS systems, and clear fault codes

\$ 150.00 ?

Towing charges

\$ 90.00 X

**\$ 15,807.75**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: