

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 18 March 2021 9:21 AM
To: Doris
Cc: SUR
Subject: RE: GBH 5885P GIA REPORT

Dear Doris,

As instructed by our client, please proceed to repair the insured vehicle **GBH 5885P at repair cost on Lump Sum basis (Excess \$1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Note: Kindly arrange our surveyor to conduct resurvey & before paint for all panels and parts.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Doris <doris@sh-motor.com>
Sent: Wednesday, 17 March 2021 5:12 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: GBH 5885P GIA REPORT

Dear Shiau Chan

Forward for you record.

Thank

Doris

From: Shiau Chan (LKKAUTO) [<mailto:siewsc@lkkauto.com>]
Sent: Wednesday, 17 March 2021 5:07 PM
To: Doris
Subject: GBH 5885P GIA REPORT

Dear Doris,

Kindly provide us the GIA report of above vehicle.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)