



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21000224/Gqd3e2-1 Date: 29/04/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 5936L	Veh. Inspected	SKA 6187U	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/21/21/VC00/024082	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	16/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PREVIA	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	JTEGD54M30A026773	Colour	SILVER	
Odometer	150983 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	KAPSEN	6 mm	
L/H Front Tyre	215/60 R16	KAPSEN	6 mm	
R/H Rear Tyre	215/60 R16	KAPSEN	6 mm	
L/H Rear Tyre	215/60 R16	KAPSEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/01/2021	Inspection Date	11/01/2021	
Survey held at	HUP LEY HUAT MOTOR SPRAY PAINTING SVS BLK 1 KAKI BUKIT AVE 6, #01-35 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	