

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21003463/ERS3Q2
Date: 12/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100500570
Claimant Vehicle No :	SLR1486M	Insured Vehicle No :	SLL803U
Date of Loss:	12/03/2021	Nature of Claim:	TP
		Claim No:	6038831216SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR1486M	Engine No:	CZC162240
Make & Model:	VOLKSWAGEN GOLF, 1.4 TSI (A)	Chassis No:	WVWZZZAUZHW120789
Reg. Date:	31/07/2017 (Man. Year: 2016)	Odometer:	38859 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Cinturato 5 mm	Rear Left Side:	Cinturato 5 mm
Front Right Side:	Cinturato 5 mm	Rear Right Side:	Cinturato 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,063.00	1,475.28	2,587.72	63.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,672.00	992.00	3,680.00	78.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,735.00	2,467.28	6,267.72	71.75
+ GST 7.00/7.00% (S\$)	611.45	172.71	438.74	71.75

Nett Amount (S\$)	9,346.45	2,639.99	6,706.46	71.75
		+ Loss of Use (3.0 x S\$50.00/day) (S\$)	150.00	
		+ Doc/Search Fee (S\$)	2.00	
		Nett Liability (S\$)	2,791.99	

INSPECTION

Date of Assignment: 17/03/2021

Date Inspected: 17/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Premium Automobiles Pte Ltd - Alexandra (HQ)
 281 Alexandra Pte Ltd, Level B2
 Singapore 159938

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	1,462.00 FS	*1,169.60 FS
2	2		*REAR SENSOR BRACKET -LH/RH	Necessary	66.00 FS	*52.48 FS
3	2		*REAR SENSOR BRACKET -LH/RH CENTER	Necessary	66.00 FS	*52.48 FS
4	1		*2 PK PLASTIC ADHESIVE	Necessary	57.00 FS	*45.28 FS
5	1		*BONDING AGENT	Necessary	60.00 FS	*47.44 FS
6	1		*REAR BUMPER FIXING PARTS	Not Necessary	97.00 FS	*- FS
7	1		*REAR BUMPER TOW COVER	Not Necessary	32.00 FS	*- FS
8	1		*REAR BUMPER SPOILER	Not Necessary	540.00 FS	*- FS
9	2		*REAR BUMPER GUIDE PROFILE -LH/RH	Broken	130.00 FS	*103.20 FS
10	1		*REAR REINFORCEMENT BEAM	Not Necessary	732.00 FS	*- FS
11	1		*REAR BUMPER SEURING STRIP	Not Necessary	112.00 FS	*- FS
12	4		*REAR BUMPER SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
13	1		*REAR LIGHT REFLECTOR LIGHT -LRH	Not Necessary	87.00 FS	*- FS
14	1		*TAILLIGHT OUTER -RH	Not Necessary	358.00 FS	*- FS
15	1		*SUNDRIES	Necessary	250.00 FS	*4.80 FS
					Total Parts (\$)	4,063.00
						1,475.28

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	100.00
2	TO DISMANTLE AND RENEW REAR BUMPER .TO REPAIR REAR END PANELLING .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,400.00	350.00
3	TO RESPRAY REAR BUMPER ,RHS REAR FENDER AND REAR END PANELLING	New	2,800.00	350.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,672.00	992.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >