

ASS. REC. BY:

REF: CS3/SMO21003474/KQvf3

Special Instruction:

Surveyor: SUN PIN ASSIGNMENT (Office)From (Person): GRACE TEO of SMO Date/Time: 17/3/2021 11:30 AM

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD: ☒ IP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLG 9738S Insured: SLN 961Kat Workshop m/s MJE Motor Tel: 9225 1391 / 9105 6323of BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642Policy No: \_\_\_\_\_ Claim No: CMTD2100828/SYH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 15.03.21  
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 17-03-21 12.05P.MPerson Contacted: JOYCE Vehicle ☒ IN ☐ OUT

| Date/Time | Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate |
|-----------|---------------------------------------------------------------------|
|           | SLG 9738S - <input checked="" type="checkbox"/>                     |
|           | SLN 961K - <input checked="" type="checkbox"/>                      |
|           |                                                                     |
| 19/3/21   | Submit PRS, repair range \$2,000-\$3,000 (5 days)                   |
|           |                                                                     |
|           |                                                                     |