

BW WORKSHOP SERVICES PTE LTD

291 KAKI BUKIT AVE 1 SHUN LI

INDUSTRIAL PARK

Singapore 416080

6289 8800

workshop_admin@bw.com.sg

GST Registration No. : 201504834E

Company Registration No. 201504834E



Estimates

ADDRESS

INDIA INTERNATIONAL

INSURANCE PTE LTD

ESTIMATES NO. 1256**DATE 16/03/2021****VIN NUMBER**

SFS1866R / GK82100868

MAKE & MODEL

HONDA SHUTTLE 1.5G CVT SENSING

ACTIVITY	QTY	RATE	AMOUNT
REAR DOOR (RH) @ \$860.40	1	688.32	688.32
REAR DOOR HINGE (RH) @ \$81.20	2	64.96	129.92
REAR DOOR CHECKER (RH) @ \$110.50	1	88.40	88.40
REAR DOOR STICKER (SET) (RH) @ \$56	1	44.80	44.80
REAR DOOR TRIM (RH) @ \$1075	1	860.00	860.00
REAR DOOR HANDLE (RH) @ \$117.60	1	94.08	94.08
REAR DOOR STRIKER (RH) @ \$58.50	1	46.80	46.80
REAR DOOR LOCK (RH) @ \$243.10	1	194.48	194.48
REAR DOOR MOLDING (RH) @ \$81.20	1	64.96	64.96
REAR DOOR GLASS MOLDING (RH) @ \$82.80	1	66.24	66.24
REAR POWER WINDOW MOTOR (RH) @ \$214.50	1	171.60	171.60
REAR FENDER (RH) @ \$684.00	1	547.20	547.20
FRONT DOOR (RH) ***REPAIR***	1		0.00
			Subtotal: 2,996.80
TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	5	200.00	1,000.00
TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	3	250.00	750.00
TO REMOVE AND REFIT DOOR GLASS	1	100.00	100.00
TO REMOVE AND REFIT REAR FENDER GLASS	1	100.00	100.00
TO REMOVE DOOR'S FITTINGS	1	120.00	120.00
			Subtotal: 2,070.00

NETS & Cash only.

Our Bank Details:-

Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd

Account Number :356-305-177-7

Please feel free to contact us again if you have any queries on our quotation.

We look forward to hearing from you soon.

SUBTOTAL	5,066.80
GST TOTAL	0.00
TOTAL	SGD 5,066.80

Accepted By

Accepted Date

NETS & Cash only.

Our Bank Details:-

Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd

Account Number :356-305-177-7