

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AXIA

Name : Parinayakam Muthukumar

Accident Date : 10-Mar-21

Vehicle No : FBC7662D

Bajaj Pulsar
Vehicle Model : DTS-1 180
Manual

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fender <i>ena ✓</i>	\$ 85.00 ✓
2	Fork inner tubes <i>su x</i>	\$ 290.00 x
2	Fork outer tubes <i>su x</i>	\$ 250.00 x
1	Fork under bracket <i>nm x</i>	\$ 185.00 x
1	Front brake disc <i>11 x</i>	\$ 135.00 x
1	Front rim shaft <i>11 x</i>	\$ 45.00 x
1	Front rim bearing <i>nm x</i>	\$ 38.00 x
1	Front wheel rim <i>su x</i>	\$ 320.00 x
1	Top cowlings <i>2 x</i>	\$ 135.00 x
1	Windshield <i>11 x</i>	\$ 85.00 x
1	Headlamp <i>scn ✓</i>	\$ 185.00 ✓
2	Front signals <i>n/scn 1pc</i>	\$ 60 120.00 1pc
1	Handle bar <i>best ✓</i>	\$ 95.00 ✓
2	Handle bar end <i>11 x</i>	\$ 50.00 x
1	Brake lever <i>scn n/c x</i>	\$ 56.00 x
1	Clutch lever <i>scn n/c x</i>	\$ 56.00 x
2	Side mirrors <i>520</i>	\$ 110.00 ✓
1	Fuel tank <i>11 x</i>	\$ 495.00 x
1	Exhaust assy <i>best ✓</i>	\$ 585.00 ✓
1	Exhaust protector <i>best ✓</i>	\$ 85.00 ✓
1	Front footrest - R/H <i>7.11 ✓</i>	\$ 35.00 ✓
1	Front footrest bracket - R/H <i>best ✓</i>	\$ 50.00 ✓
1	Brake pedal <i>2 x</i>	\$ 42.00 x
1	Rear fender <i>D.S ✓</i>	\$ 65.00 ✓
1	Rear tailboard <i>cm ✓</i>	\$ 145.00 ✓
1	Rear taillamp <i>cm ✓</i>	\$ 180.00 ✓
1	Rear signal - R/H <i>11 x</i>	\$ 65.00 x
1	Crash bar (1 set) <i>2 x</i>	\$ 150.00 x
1	Rear footrest - R/H <i>dye ✓</i>	\$ 28.00 ✓
1	Rear footrest bracket - R/H <i>11 x</i>	\$ 48.00 x
		\$ 4,213.00
	Less 10%	\$ 421.30
		\$ 3,791.70

*not Alford
18/3/21
1/s \$1300
Telephone Number
H Long*

1708

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Parinayakam Muthukumar

Accident Date : 10-Mar-21

Vehicle No : FBC7662D

Bajaj Pulsar
Vehicle Model : DTS-1 180
Manual

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	sent Rear 10	\$	28.00	10
2	Fork oils	11X	\$	30.00	X
2	Fork oil seals	11X	\$	56.00	X
1	Steering cone (1 set)	11X	\$	75.00	X
1	Rear box	sent X	\$	380.00	X
1	Rear box bracket	12X	\$	160.00	X
			\$	729.00	

S/No. Labour

1	To provide transport (LOD)	\$	50.00	✓
2	To check wiring and reset headlamp focusing	\$	117 80.00	X
3	To repair body frame	\$	117 350.00	X
4	To provide labour	\$	300 400.00	
		\$	880.00	

Grand Total

\$ 5,400.70

Singapore Dollars: Five Thousand Four Hundred and Cents: Seventy only

1897.2
1897

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIKE RECOVERY SERVICE

HP: 8298 6622

Business Reg. No: 201216510M

CASH SALE

NO: 01658

Date: 12/3/21

Particular: _____

Vehicle No: FBC 7662 D

Model No: BAJAJ

From: T.P. POUND TO RAN FODK SINGH To: SROFIA

Time: (Day/Night): _____

Others: _____

CASH \$: 50K

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or others misdemeanour to your vehicle while being towed.