

Our Job Ref No : 305458926
Date : 19/03/21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : TAUFIKH
Vehicle Reg No. : SHD6990L

Fax :


16/03/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- Z The repair job shall bill to: TOKIO MARINE SLG9024T
2. The finalized amount shall be:
- | | |
|---|--|
| (a) Spare Parts after List discount | <u>\$2,079.28</u> |
| (b) Labour Charges | <u>\$810.00 \$810</u> |
| Total for Part-By-Part Repair Cost | <u>\$2,900.28 \$2900.28</u> |
| (c.) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | |
| Final Lumpsum Repair cost | |

3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : taufikh
Name : Taufikh
Date : 22/4/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305458926
 REGN NO : SHD6990L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 25.02.2021
 DATE/TIME IN : 16.03.2021 15:20
 ACCIDENT DATE : 16.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0003 04-01-0104-0852-G	REFLECTOR/REFLEX ASSY-RR	1	41.45	20.00	33.16
0004 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0005 09-01-0104-2207-G	UNIT ASSY-REAR CORNER RAD	1	1,625.00	20.00	1,300.00

SUB-TOTAL : 2,079.28

JOB NATURE

0000 L	MERIMEN FEE	11.00
0001 PB	PANEL BEATING	350.00
0002 SP	SPRAYPAINT CHARGE	250.00
0003 20-22	REMOVE/REFIX REVERSE SENSOR	30.00
0004 L	DIAGNOSE/RESET ERROR FAULT CODE	2000 180

810
 SUB-TOTAL : ~~881.00~~