

# OTOR REPAIRS SERVICES PTE LTD

IVE #08-03 SIN MING AUTOCITY SINGAPORE 575722  
 96 / 6454 8007 Fax No. : 6554 2640  
 @hotmail.sg  
 199001597D

Page 1 / 2

KWANG  
 ST 11, #08-399  
 25

Claim Department

*Not Authorized*  
*1/Qty @ 3000/pc*  
*Priming After Paint*  
*5 days*

Estimate : ES003422

Date : 16/03/2021  
 Vehicle Num. : SMK6522J  
 Make/Model : HONDA VEZEL  
 Chassis/Eng# :  
 Accident Date : 14/03/2021  
 Claim No. :  
 Reference :  
 Policy No. : 5116730721

| Particular                                 | Unit Price | Amount S\$ |
|--------------------------------------------|------------|------------|
| LIST ITEMS :                               |            |            |
| REAR BOOT COVER                            |            | 1,050.00 ✓ |
| REAR BOOT COVER WINDSCREEN MOULDING        |            | 120.00 ✓   |
| REAR BOOT COVER INNER LOCK                 |            | 157.10 ✓   |
| REAR BOOT COVER STAY                       | 180.00     | 360.00 X   |
| REAR BOOT COVER LOGO                       |            | 15.70 X    |
| REAR BOOT COVER NUMBER PLATE LAMP MOULDING |            | 225.70 X   |
| REAR BOOT COVER REFLECTOR LH               |            | 360.00 X   |
| REAR BOOT COVER REFLECTOR RH               |            | 360.00 X   |
| REAR BOOT COVER VEZEL EMBLEM               |            | 43.00 ✓    |
| REAR BOOT COVER WEATHERSTRIP               |            | 101.30 ✓   |
| REAR BOOT END PANEL                        |            | 411.90 X   |
| REAR BOOT END PANEL TOP GARNISH            |            | 92.30 X    |
| REAR BUMPER                                |            | 532.10 ✓   |
| REAR BOOT SIDE REFLECTOR L/H               |            | 141.00 ✓   |
| REAR BUMPER SIDE REFLECTOR R/H             |            | 141.00 X   |
| REAR BUMPER SIDE RETAINER LH               |            | 17.50 ✓    |
| REAR BUMPER SIDE RETAINER RH               |            | 17.50 X    |
| REAR BUMPER CLIPS                          |            | 21.00 ✓    |
| REAR BUMPER SIDE GARNISH LH                | 3.50       | 195.00 ✓   |
| REAR BOOT LOCK SENSOR                      |            | 175.50 ✓   |
| REAR BOOT FLOOR BOARD UNDER COVER          |            | 190.00 ✓   |
| List Total S\$ :                           |            | 4,727.60   |
| 20.00% Discount S\$ :                      |            | 945.52     |
|                                            |            | 3,782.08   |
| SPECIAL NETT ITEMS :                       |            |            |
| 1 SET OF WINDSCREEN SEALANT                |            | 120.00 ✓   |
| Special Nett Total S\$ :                   |            | 120.00     |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

CONTINUE / ...

# OTOR REPAIRS SERVICES PTE LTD

RIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

96 / 6454 8007 Fax No. : 6554 2640

@hotmail.sg

199001597D

Page 2 / 2

KWANG

T 11, #08-399

5

im Department

Estimate : ES003422

Date : 16/03/2021

Vehicle Num. : SMK6522J

Make/Model : HONDA VEZEL

Chassis/Eng# :

Accident Date : 14/03/2021

Claim No. :

Reference :

Policy No. : 5116730721

Particular

Unit Price

Amount S\$

## LABOUR :

1. REMOVE AND REFIX REAR BOOT COVER WINDSCREEN GLASS
2. REMOVE AND REFIX REAR BOOT COVER VIDEO CAMERA
3. REMOVE AND REFIX REAR BOOT REVERSE CAMERA
4. SUPPLY & INSTALL ONE SET OF REAR REVERSE SENSOR
5. CHECK & REPAIR WIRING FOR REAR BOOT COVER, REAR LAMP
6. SPRAY ANTI-RUST COATING ON ACCIDENT AFFECTED PORTIONS
7. SPRAY PAINT ON ACCIDENT AFFECTED PORTIONS
8. REMOVE AND REFIX REAR BOOT COVER TOP SPOILER
9. LABOUR CHARGE FOR REPAIRING, REPLACING, ADJUSTING, KNOCKING AND WELDING THE DAMAGED PARTS, STRAIGHTEN THE ABOVE

1201  
180.00  
150.00 501  
150.00 501  
280.00  
120.00 201  
180.00 301  
900.00  
180.00  
5501 1,200.00  
3,340.00

Labour Total S\$ :

n Thousand Two Hundred Forty-Two & Cents Eight Only

E. & O.E.

Total S\$ :

7,242.08

OTOR REPAIRS SERVICES PTE LTD