



Section A - Accident Details

Registration Number	SHB817E
Case Reference Number	TAX/03/21/2043
Registration Date	10/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	GOH CHEE KEON LOURENS
Type of Accident	Side Swipe
Accident Date and Time	14/3/2021 9:50 AM
Accident Reported Date and Time	15/3/2021 9:04 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110062
Special Instruction to ARC, if any	TP / RIGHT REAR PORTION / CHINA TAIPING - LKK
Prepared Date and Time	16/3/2021 11:52 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$2,772.00	\$517.00
Total Spare Part Cost	\$6,778.83	\$618.07
Total Other Cost	\$850.00	\$120.00
TOTAL COST	\$11,245.83	\$1,655.07
Lump Sum Total	\$11,250.00	\$1,650.00 (L/S)
Number of Repair Days	7.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / China Taiping
ARC / Surveyor Sign Off Date	19/03/2021 8:58 AM	19/03/2021 8:49 AM
Signature		
Remarks	Total number of repair days = 3 days. SUP = 0 day.	L/S, after paint photo.

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-2103-0619	Invoice Number	
Quotation Date	31.03.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$845.00	\$400.00 /
Total Labour	\$845.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY RH REAR DOOR	\$378.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00 /
RESPRAY WHEEL CAP	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 /
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$117.00 100
Total Spray Painting & Panel Beating	\$2,772.00	\$517.00 500

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$150.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$850.00	\$120.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67003472 10	PANEL SUB-ASSY, REAR DOOR, RH	0.00	\$1,243.90	0.00	\$0.00	Replace	Not Given X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given X
		75850479 10	MOULDING ASSY, BODY ROCKER PANEL, RH	0.00	\$576.00	0.00	\$0.00	Replace	Not Given X
		76085479 16	SPOILER SUB-ASSY, REAR	0.00	\$1,322.10	0.00	\$0.00	Replace	Not Given X
			STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given X

SVC
SVC
SVC
SVC
SVC

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	Notes
			SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given X	SVC
7540348010			EMBLEM SUB-ASSY REAR	0.00	\$46.30	0.00	\$0.00	Replace	Not Given X	SVC
7544247130			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	0.00	\$52.30	0.00	\$0.00	Replace	Not Given X	SVC
7544147090			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	0.00	\$52.30	0.00	\$0.00	Replace	Not Given X	SVC
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	0.00	\$891.20	0.00	\$0.00	Replace	Not Given X	SVC
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	\$929.60	0.00	\$0.00	Replace	Not Given X	SVC
8149747020			COVER, REAR COMBINATION LAMP, RH	1.00	\$54.00	100.00	\$0.00	Replace	Old Damage X	SVC
8155147281			LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$438.10	100.00	\$0.00	Replace	Old Damage X	SVC
5839847050			COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given X	SVC
8158147010			LENS & BODY ASSY, RR BUMPER, RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given X	SVC
5246147010			PAD, RR BUMPER, CTR	0.00	\$2.20	0.00	\$0.00	Replace	Not Given X	SVC
5245347010			GUARD, RR BUMPER, LOWER	0.00	\$558.30	0.00	\$0.00	Replace	Not Given X	SVC
5259147050			SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given X	SVC
5257547040			RETAINER, RR BUMPER, RH	1.00	\$112.70	25.00	\$84.53	Replace	Replace	BR
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	NEC
5256547900			FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given X	SVC
5219147030			SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given X	SVC
5246247010			PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace	NEC
5246247020			PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace	NEC
5246247030			PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace	NEC
5216116010			CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	NEC
5215947913			COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace	CRU
6294047010			DUCT ASSY, QUARTER VENT, RH & LH	0.00	\$65.00	0.00	\$0.00	Replace	Check X	SVC
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X	SVC
4261147450			WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given X	SVC
4260247180			CAP SUB-ASSY, WHEEL	1.00	\$175.80	25.00	\$131.85	Replace	Replace	SCR
6563747060			LINER, REAR FENDER, RH	0.00	\$135.80	0.00	\$0.00	Replace	Check X	SVC
6160147150			PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	100.00	\$0.00	Replace	Repair	R
Total					\$10,740.84		\$682.66			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		5256547900	FILLER, RR BUMPER, RH	1.00	\$119.90	25.00	\$89.93	Replace	Replace
Total					119.90		89.93		

772.59 /
 -20%
 + 618.07 /
 + 100.00 /
 + ~~637.00~~ 620

 1655.07
 1,638.07

45 \$1650 / -
 3 days
 SHB 817E