

Section A - Accident Details

Registration Number	SHB5808Z
Case Reference Number	TAX/03/21/2044
Registration Date	20/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	LIM THIAM HOE (LIN TIANHE)
Type of Accident	Head On
Accident Date and Time	14/3/2021 11:18 PM
Accident Reported Date and Time	15/3/2021 9:52 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110063
Special Instruction to ARC, if any	TOWED \$40
Prepared Date and Time	16/3/2021 1:59 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

LKK Auto Consultants hence notify the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$400.00
Total Spray Cost	\$2,052.00	\$450.00
Total Spare Part Cost	\$14,177.40	\$3,983.20
Total Other Cost	\$836.00	\$130.00
TOTAL COST	\$18,079.40	\$4,963.20 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / China Taiping
ARC / Surveyor Sign Off Date	16/03/2021 2:38 PM	16/03/2021 4:19 PM
Signature		
Remarks		P/P, Before paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2104-0002	Invoice Number	
Quotation Date	01.04.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$1,014.00	\$400.00 /
Total Labour	\$1,014.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 /
TO REPSRAY FRONT HOOD	\$378.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00 /
TO RESPRAY APRON PANEL RH	\$180.00	\$0.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$0.00
TO RESPRAY RIM	\$180.00	\$50.00 /
Total Spray Painting & Panel Beating	\$2,052.00	\$450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00 /
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00 /
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00 /
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$836.00	\$130.00 /

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53851-47061	PAD, FR WHEEL RH	0.00	\$59.60	0.00	\$0.00	Replace	Not Given X
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$54.60	25.00	\$40.95	Replace	Replace /
		53875-47120	LINER, FR FENDER, RH	1.00	\$202.50	25.00	\$151.88	Replace	Replace /
		53801-47080	FENDER SUB-ASSY, FR, RH	1.00	\$977.80	25.00	\$733.35	Replace	Replace /
		85330-47100	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	0.00	\$292.40	0.00	\$0.00	Replace	Check X
		90099-33080	HOSE, WINDSHIELD WASHER	0.00	\$16.80	0.00	\$0.00	Replace	Not Given X
		85315-47160	WIPER WASHER JAR	1.00	\$219.10	25.00	\$164.33	Replace	Replace /
		85319-47170	WIPER WASHER INLET	0.00	\$67.00	0.00	\$0.00	Replace	Check X
		81016-47860	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$3,772.50	0.00	\$0.00	Replace	Not Given X

SVC
NEC
DEF
CR4
SVC
SVC
CR4
SVC
SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/04/2021

User ID : PohSuan

81145-47890	UNIT , HEADLAMP , RH	1.00	\$2,637.60	10.00	\$2,373.84	Replace	Replace	CRU
53202-47901	SUPPORT S/A RH	0.00	\$245.10	0.00	\$0.00	Replace	Check	X
53213-47050	SUPPORT, RADIATOR UPPER RH	0.00	\$78.90	0.00	\$0.00	Replace	Not Given	X
53630-47091	CABLE ASSY, HOOD	0.00	\$54.90	0.00	\$0.00	Replace	Not Given	X
53420-47130	HINGE ASSY, HOOD, LH	0.00	\$58.90	0.00	\$0.00	Replace	Not Given	X
53410-47130	HINGE ASSY, HOOD, RH	0.00	\$58.90	0.00	\$0.00	Replace	Not Given	X
53301-47110	HOOD SUB-ASSY	0.00	\$983.10	0.00	\$0.00	Replace	Not Given	X
51451-12120	COVER ASSY, ENGINE	0.00	\$241.90	0.00	\$0.00	Replace	Not Given	X
53101-47100	GRILLE SUB-ASSY	0.00	\$422.50	0.00	\$0.00	Replace	Not Given	X
52102-47020	EXTENSION SUB-ASSY, RH	0.00	\$120.10	0.00	\$0.00	Replace	Not Given	X
52132-47010	REINFORCEMENT FRONT LOWER	0.00	\$246.10	0.00	\$0.00	Replace	Check	X
52618-47130	ABSORBER, FR BUMPER LOWER	0.00	\$132.70	0.00	\$0.00	Replace	Check	X
52021-47110	REINFORCEMENT FRONT UPPER	0.00	\$716.60	0.00	\$0.00	Replace	Check	X
52611-47210	ABSORBER, FR BUMPER	0.00	\$80.20	0.00	\$0.00	Replace	Check	X
52115-47050	SUPPORT, FR BUMPER RH	0.00	\$80.10	0.00	\$0.00	Replace	Check	X
52712-47040	MOULDING, FRONT BUMPER SIDE, RH	1.00	\$95.60	25.00	\$71.70	Replace	Replace	SCR
53395-47060	SEAL, HOOD TO FR END	0.00	\$85.50	0.00	\$0.00	Replace	Check	X
81210-12240	LAMP ASSY, FOG, RH	0.00	\$237.10	0.00	\$0.00	Replace	Not Given	X
53112-47310	GRILLE, RADIATOR	0.00	\$178.60	0.00	\$0.00	Replace	Check	X
52127-47911	COVER, FR BUMPER RH	1.00	\$30.20	25.00	\$22.65	Replace	Replace	Mis
52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.50	25.00	\$33.75	Replace	Replace	Nec
52119-47980	COVER, FR BUMPER	1.00	\$521.00	25.00	\$390.75	Replace	Replace	CRU
53827-47050	PROTECTOR, FR FENDER RH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given	X
	STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X
67001-47153	PANEL SUB-ASSY, FRONT DOOR RH	0.00	\$1,300.70	0.00	\$0.00	Replace	Not Given	X
42611-47450	WHEEL, DISC FRONT	1.00	\$1,879.40	100.00	\$0.00	Replace	Repair	R
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
53701-47111	APRON SUB-ASSY, FRONT FENDER, RH	0.00	\$979.40	0.00	\$0.00	Replace	Check	X
Total			\$17,412.54		\$3,983.20			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

3983.20 /
+ 400.00 /
+ 580.00 /
4963.20 /

P/P
\$4,963.20
3 days
SHB 58082