## 16th MAR 2021

United Overseas Insurance Ltd

3 Anson Road, #28-01 Springleaf Tower Singapore 079909

Attention: Motor Vehicle Claim Department

Dear Sir / Mdm,

## THIRD PARTY

We are currently assisting this Vehicle with the SLN961K to make accident claims against SLG9738S which eventuated on 15/03/2021. This vehicle is insured by United Overseas Insurance Ltd

We seek your co-operation to get the vehicle surveyed by your Accredited surveyors.

Once arrangement is being made, please do notify us to let us have the Ample time to get things arranged for the surveyor.

Your Faithfully,

Wega Engineering Pte Ltd

Leong Chee Kwong Claims Advisor

Mobile No: 84917768

## WEGA ENGINEERING PTE LTD

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref:

United Overseas Insurance Ltd

3 Anson Road, #28-01 Springleaf

Tower Singapore 079909

Date

16/3/2021

Vehicle No :

SLN961K

Chassis No : WBA2E320605H46089

Make/Model : BMW 216D SE AUTO

Year

: 2017

| 5/N | Qty | Description                             | Unit Price |               | Amount |  |
|-----|-----|---|------------|---------------|--------|--|
| 1   | 1pc | FRONT BONNET                            |            | 1,045.00      | 5      | The second secon |
| 2   | 1pc | FRONT BONNET HIAGE RH                   | s          | 137.50        | \$     |  |
| 3   | 1pc | FRONT BONNET HIAGE LH                   | s          | 137.50        | \$     |  |
| 4   | 1pc | FRONT BUMPER                            |            | 1,140.00      | S      | 137.50   |
| 5   | 1pc | FRONT HEADLAMP RH                       | 5          | 1,078.00      | 1000   |  |
| 6   | 1pc | FRONT FENDER RH                         | \$         | 70 Contractor | \$     | 1,078.00   |
| 7   | 1pc | FRONT HEADLAMP BRACKET RH ( TOP PANAL ) | - 37.      | 649.00        | \$     | 649.00   |
| 8   | 1pc | FRONT BUMPER BRACKET RH                 | \$         | 61.00         | S      | 61.00  |
| 9   | 1pc | FRONT FOG LAMP COVER RH                 | \$         | 53.00         | 5      | 53.00  |
| 10  | 1pc | FRONT FOG LAMP RH                       | \$         | 104.00        | 5      | 104.00   |
| 11  | 1pc | FRONT SPORT RIM RH                      | 5          | 245.00        | 5      | 245.00   |
| 12  | 1pc | FRONT TYRE RH                           | \$         | 1,473.00      | 5      | 1,473.00   |
| 13  | 1pc | FRONT KNUCKER ARM RH                    | \$         | 225.00        | 5      | 225.00   |
| 14  | 1pc | FRONT WHEEL HUP RH                      | \$         | 758.00        | \$     | 758.00   |
| 15  | 1pc | FRONT WHEEL BEARING RH                  | \$         | 589.00        | \$     | 589.00   |
| 16  | 1pc | FRONT LOWER ARM RH                      | \$         | 280.00        | \$     | 280.00   |
| 18  | 1pc | FRONT ABSORBER RH                       | \$         | 487.00        | \$     | 487.00   |
| 19  | 1pc | FRONT TIE ROD RH                        | s          | 484.00        | \$     | 484.00   |
| 20  | 1pc |   | \$         | 166.00        | \$     | 166.00   |
| 21  | 1pc | FRONT TIE ROD INNER RH                  | \$         | 122.00        | \$     | 122.00   |
| 22  | 1pc | FRONT TORSION BAR LINK RH               | \$         | 125.00        | \$     | 125.00   |
| 2.2 | The | FRONT DRIVE SHAFT ASSY RH               | \$ 2       | ,676.00       | \$     | 2,676.00   |

## Labour Charges

| 1   | To check wiring and system function                                   |    | 130.00   |
|-----|---|----|----------|
| 2   | To wheel alighment / tyre balancing                                   | >  | 120.00   |
| 3   | To remove and refix undercarriage                                     | \$ | 120.00   |
| 4   |   | \$ | 600.00   |
|     | To respray accident front portion                                     | \$ | 1,000.00 |
| 5   | To knocking and welding front portion                                 | \$ | 1,000.00 |
| 6   | To apply rust proofing to affected area                               | 5  | 150.00   |
| 7   | To replace front tyre   | ě  | 55.00    |
| 8   | To check for function and aligment headlamp                           | 9  |          |
| 9   | To conduct re-programme and setting of ecu system to clear fault code | 5  | 80.00    |
| 7.0 | and setting of eco system to clear fault code                         | \$ | 150.00   |

**Grand Total** 

\$ 15,310.00

Wega Engineering te Ltd

Authorised Signature Leong Chee Kwong Mobile No: 84917768